

AUTOMOBILE ASSESSMENT REPORT

TO: R MUNGAM S/O APASAMY
C/O: V-TECH AUTO SERVICE
NO.1 SOON LEE STREET #06-04/05 PIONEER
CENTRE
SINGAPORE 627605

Our Reference: 917/VT272
Date: 05 OCTOBER 2017

ASSESSMENT OF VEHICLE NO. SBY 1937 K DATE OF LOSS: 23/09/2017

We have carried out a physical assessment of SBY1937K at **V-TECH AUTO SERVICE**,
No. 1 Soon Lee Street #06-04/05 Pioneer Centre Singapore 627605, according to your
instruction on 25 SEPTEMBER 2017 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SBY 1937 K
Make & Model: MERCEDES BENZ 190 AUTO
Year of Registration: 1990
Engine Capacity: 1997
Chassis No.: WDB2010232F715110
Engine No.: 10292422016095
Colour: BLUE
Mileage (km): 108907

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size/Thread: YOKOHAMA 195/60 R15 - 75%
LH Make/Size/Thread: YOKOHAMA 195/60 R15 - 75%

Rear

RH Make/Size/Thread: BRIDGESTONE 195/60 R15 - 75%
LH Make/Size/Thread: BRIDGESTONE 195/60 R15 - 75%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

5. REMARKS

Market Value: Na
Salvage Value: Na
Repair Limit: Na

Estimated Amount: \$ 8,204.00
Adjusted Amount: \$ 5,929.00 (Lump Sum of \$5,000.00)
Estimated Repair Days: 6 days


Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.



ASSESSMENT REPORT FOR VEHICLE NO. SBY 1937 K

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	1,039.00	-
1	FRONT BONNET GRILLE	Repair	380.00	-
1	FRONT BONNET MECHANISM LOCK <i>X SVC</i>	Bent	68.00	68.00 <i>X</i>
1	FRONT RH HEADLAMP	Cracked	762.00	762.00 <i>/</i>
1	FRONT RH HEADLAMP APRON PANEL	Bent	48.00	48.00 <i>/</i>
1	FRONT RH HEADLAMP SIDE GARNISH	Cracked	68.00	68.00 <i>/</i>
1	FRONT RH SIDE SIGNAL LAMP <i>X SVC</i>	Cracked	102.00	102.00 <i>X</i>
1	FRONT BUMPER	Cracked	1,105.00	1,105.00 <i>/</i>
1	FRONT BUMPER PROTECTOR	Cracked	169.00	169.00 <i>/</i>
2	FRONT BUMPER SIDE BRACKET L/R	Bent	176.00	176.00 <i>/</i>
2	FRONT BUMPER TOP CHROME L/R <i>X SVC</i>	Bent	378.00	378.00 <i>X</i>
1	FRONT BUMPER TOWING COVER <i>X SVC</i>	Cut	60.00	60.00 <i>X</i>
1	FRONT BUMPER REINFORCEMENT <i>X SVC</i>	Bent	832.00	832.00 <i>X</i>
2	FRONT BUMPER REINFORCEMENT BRACKET L/R <i>X SVC</i>	Bent	56.00	56.00 <i>X</i>
1	FRONT RH FENDER	Repair	416.00	-
			<i>2328</i>	
			<i>10%: 20952</i>	
			5,659.00	3,824.00
Less 0% discount			0.00	0.00
Parts Total:			5,659.00	3,824.00

SPECIAL NETT ITEMS

1	FRONT BUMPER CLIPS - SET	Necessary	30.00	30.00 <i>/</i>
1	FRONT BUMPER NUMBER PLATE <i>X SVC</i>	Bent	25.00	25.00 <i>X</i>
1	FRONT BUMPER NUMBER PLATE GARNISH <i>X SVC</i>	Cracked	50.00	50.00 <i>X</i>
Special Nett Total :			105.00	105.00

ASSESSMENT REPORT FOR VEHICLE NO. SBY 1937 K

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	120.00	100.00 70
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	800.00 400
3	To provide labour, workmanship to change the above damaged bodyparts, repair and re-construct consistent to the accident.	1,200.00	1,000.00 200
4	To apply anti-rust chemical on repaired and replaced panel.	120.00	100.00 X
Labour Total :		2,440.00	2,000.00
TOTAL (PARTS & LABOUR) \$		8,204.00	5,929.00

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is **\$5,000.00** (SINGAPORE DOLLARS FIVE THOUSAND ONLY)



Amas Ong
Automobile Assessor

2755.2
 20%: 2200
 3 Days