



19 Lorong 8 Toa Payoh  
Singapore 319255



**ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR**

|                                            |                                        |
|--------------------------------------------|----------------------------------------|
| <b>REG NO: SBW54A</b>                      | <b>MODEL : FORESTER 2.0I-L AWD CVT</b> |
| <b>REF NO:INS/IC/CHI/0050/2021</b>         | <b>YEAR: 20-NOV-2018</b>               |
| <b>ENGINE NO: FB20YE50257</b>              | <b>CHASSIS NO: JF1SJ5KC5JG112545</b>   |
| <b>DOA: 02/03/2021</b>                     | <b>TOA: 1925HRS</b>                    |
| <b>TYPE OF CLAIM: 3<sup>RD</sup> PARTY</b> | <b>INS COMPANY: ERGO</b>               |

| <b>S/N</b> | <b>NATURE OF JOB</b>                                          | <b>AMOUNT</b>     |
|------------|---------------------------------------------------------------|-------------------|
| 1.         | REPAIR/REPLACE REAR BUMPER, TAILGATE, BEAM & END PANEL        | \$3360.00         |
| 2.         | RESPRAY REAR BUMPER, TAILGATE, BEAM & END PANEL               | \$2620.00         |
| 3.         | DISMENTLE & REFIX UNDERCARRAIGE TO FACILITATE REPAIR          | \$900.00          |
| 4.         | REMOVE & REFIX EXHAUST                                        | \$150.00          |
| 5.         | TRANSFER TAILGATE MECHANISM                                   | \$150.00          |
| 6.         | WHEEL ALIGNMENT                                               | \$200.00          |
| 7.         | REMOVE & REFIX CARPET,SEATS TO FACILITATE REPAIRS             | \$400.00          |
| 8.         | REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS | \$150.00          |
| 9.         | FAULT DIAGNOSTIC                                              | \$280.00          |
| 10.        | REMOVE & INSTALL REAR WINDSCREEN                              | \$300.00          |
| 11.        | TO REMOVE & REFIX FUEL TANK                                   | \$200.00          |
| 12.        | TO CONDUCT REAR LIGHTING TEST                                 | \$50.00           |
| 13.        | TO CONDUCT REAR PROTECTANT COATING                            | \$500.00          |
| 14.        | TO CONDUCT REAR NATI RUST COATING                             | \$580.00          |
| 15.        | TO SUPPLY & INSTALL REVERSE SENSOR – 2 EYES                   | \$300.00          |
| 16.        | TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM               | \$145.00          |
| 17.        | SUNDRIES                                                      | \$100.00          |
|            | <b>Total Labour</b>                                           | <b>\$10385.00</b> |

|                       |   |
|-----------------------|---|
| <b>DATE APPROVAL:</b> |   |
| <b>TIME APPROVAL:</b> |   |
| <b>SURVEY BY:</b>     |   |
| <b>HP / EMAIL:</b>    | / |
| <b>BEFORE PAINT:</b>  |   |
| <b>DAYS GIVEN:</b>    |   |

Estimate

Date 03 / 03 / 2021

001 / 002

|         |                      |                |                   |
|---------|----------------------|----------------|-------------------|
| Name    | QUOTATION FOR SBW54A | Tel (Home)     |                   |
| Address |                      | Tel (Office)   |                   |
| E-Mail  |                      | Tel (Portable) |                   |
|         |                      | Fax            |                   |
|         |                      | Model Name     | S13               |
|         |                      | Body Model     | SJ5EK7C           |
|         |                      | Vin-Code       | JF1SJ5KC5JG112545 |

| Part Number  | Part Code Name                    | Part Code       | Q'ty | Price    |
|--------------|-----------------------------------|-----------------|------|----------|
| 63019SG000   | GLASS-REAR GATE                   | FIG-621 63011   | 1    | 799.20   |
| 63232SG010   | RUBBER-REAR GATE                  | FIG-621 63232   | 1    | 12.60    |
| 63232SG000   | DAM RUBBER-REAR GATE GLASS        | FIG-621 63232C  | 2    | 7.20     |
| 60809SG0109P | PANEL-REAR GATE                   | FIG-620 60810   | 1    | 1,072.80 |
| 63032FG102   | LATCH & ACTUATOR-REAR GATE        | FIG-622 63176A  | 1    | 144.00   |
| 63264AG100   | STRIKER-REAR GATE                 | FIG-622 63264   | 1    | 21.60    |
| 59122SG060   | MUD GUARD, REAR RIGHT             | FIG-541 59112   | 1    | 57.60    |
| 59122SG070   | MUD GUARD, REAR LEFT              | FIG-541 59112A  | 1    | 57.60    |
| 63516SG001   | WEATHER STRIP-REAR GATE           | FIG-901 63516   | 1    | 111.60   |
| 94026SG000VH | TRIM PANEL-REAR SKIRT             | FIG-940 94046   | 1    | 36.00    |
| 57704SG012   | BUMPER-FACE, REAR                 | FIG-591 57704A  | 1    | 540.00   |
| 57711SG0219P | BACK BEAM COMPLETE-REAR           | FIG-591 57711D  | 1    | 288.00   |
| 57707SG080   | BRACKET-REAR BUMPER SIDE, RIGHT   | FIG-591 57707H  | 1    | 14.40    |
| 57707SG090   | BRACKET-REAR BUMPER SIDE, LEFT    | FIG-591 57707I  | 1    | 14.40    |
| 57707SG060   | BRACKET-REAR BUMPER CORNER, RIGHT | FIG-591 57707AC | 1    | 18.00    |
| 57707SG070   | BRACKET-REAR BUMPER CORNER, LEFT  | FIG-591 57707AD | 1    | 18.00    |
| Page-Total   |                                   |                 |      | 3,213.00 |

|      |
|------|
| Memo |
|      |

|             |
|-------------|
| Grand Total |
| 3,640.80    |

|  |
|--|
|  |
|--|

|     |
|-----|
| Tel |
|-----|

Estimate

Date 03 / 03 / 2021

002 / 002

|         |                      |                |                   |
|---------|----------------------|----------------|-------------------|
| Name    | QUOTATION FOR SBW54A | Tel (Home)     |                   |
| Address |                      | Tel (Office)   |                   |
| E-Mail  |                      | Tel (Portable) |                   |
|         |                      | Fax            |                   |
|         |                      | Model Name     | S13               |
|         |                      | Body Model     | SJ5EK7C           |
|         |                      | Vin-Code       | JF1SJ5KC5JG112545 |

| Part Number  | Part Code Name                  | Part Code       | Q'ty | Price    |
|--------------|---------------------------------|-----------------|------|----------|
| 57731SG010NN | COVER-REAR BUMPER               | FIG-591 57731C  | 1    | 12.60    |
| 57731SG060   | COVER-REAR BUMPER               | FIG-591 57731CA | 1    | 14.40    |
| 84281SC000   | REFLEX REFLECTOR ASSEMBLY-RIGHT | FIG-842 84281   | 1    | 20.40    |
| 84281SC010   | REFLEX REFLECTOR ASSEMBLY-LEFT  | FIG-842 84281A  | 1    | 20.40    |
| 91111SG000   | GARNISH ASSEMBLY-REAR GATE, B   | FIG-914 91111P  | 1    | 144.00   |
| 91713SG000   | PROTECTOR-REAR GARNISH          | FIG-914 91713   | 1    | 21.60    |
| 91713SG010   | PROTECTOR-REAR GARNISH          | FIG-914 91713C  | 2    | 10.80    |
| 93033SG001   | ORNAMENT                        | FIG-914 93033D  | 1    | 79.20    |
| 93079SG000   | LETTER MARK-REAR                | FIG-919 93073Y  | 1    | 39.60    |
| 93079SG030   | LETTER MARK-REAR                | FIG-919 93073Y  | 1    | 64.80    |
|              |                                 | Page-Total      |      | 427.80   |
|              |                                 | Sub-Total       |      | 3,640.80 |
|              |                                 | Total           |      | 3,640.80 |
|              |                                 | Tax             |      | 0.00     |
|              |                                 | Grand Total     |      | 3,640.80 |

|      |
|------|
| Memo |
|      |

|             |
|-------------|
| Grand Total |
| 3,640.80    |

|  |
|--|
|  |
|--|

|     |
|-----|
| Tel |
|-----|