

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SBW54A	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/0050/2021	YEAR: 20-NOV-2018
ENGINE NO: FB20YE50257	CHASSIS NO: JF1SJ5KC5JG112545
DOA: 02/03/2021	TOA: 1925HRS
TYPE OF CLAIM: 3RD PARTY	INS COMPANY: ERGO

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER, TAILGATE, BEAM & END PANEL ✓	\$3360.00 1120 ✓
2.	RESPRAY REAR BUMPER, TAILGATE, BEAM & END PANEL ✓	\$2620.00 840 ✓
3.	DISMENTLE & REFIX UNDERCARRAIGE TO FACILITATE REPAIR nrx	\$900.00 X
4.	REMOVE & REFIX EXHAUST nrx	\$150.00 X
5.	TRANSFER TAILGATE MECHANISM	\$150.00 ✓
6.	WHEEL ALIGNMENT nrx	\$200.00 X
7.	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIRS nrx	\$400.00 ?
8.	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS	\$150.00 ✓
9.	FAULT DIAGNOSTIC nrx	\$280.00 X
10.	REMOVE & INSTALL REAR WINDSCREEN	\$300.00 ✓
11.	TO REMOVE & REFIX FUEL TANK nrx	\$200.00 X
12.	TO CONDUCT REAR LIGHTING TEST	\$50.00 30 ✓
13.	TO CONDUCT REAR PROTECTANT COATING x	\$500.00 X
14.	TO CONDUCT REAR NATI RUST COATING nrx	\$580.00 290 ?
15.	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES x	\$300.00 ?
16.	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM ✓	\$145.00 ✓
17.	SUNDRIES	\$100.00 20 ✓
Total Labour		\$10385.00 ✓

DATE APPROVAL:	23/3/21 @ 3 pm.
TIME APPROVAL:	
SURVEY BY:	Tauflin
HP / EMAIL:	62563561 / 97495749 tauflin@khawto.com
BEFORE PAINT:	M
DAYS GIVEN:	4-5 days

Estimate

Date 03 / 03 / 2021

001 / 002

Name	QUOTATION FOR SBW54A	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG112545

Part Number	Part Code Name	Part Code	Q'ty	Price
63019SG000	GLASS-REAR GATE	FIG-621 63011	1	rel ✓ 799.20 ✓
63232SG010	RUBBER-REAR GATE	FIG-621 63232	1	rel ✓ 12.60 ✓
63232SG000	DAM RUBBER-REAR GATE GLASS	FIG-621 63232C	2	rel ✓ 7.20 ✓
60809SG0109P	PANEL-REAR GATE	FIG-620 60810	1	bt ✓ 1,072.80 ✓
63032FG102	LATCH & ACTUATOR-REAR GATE	FIG-622 63176A	1	X 144.00
63264AG100	STRIKER-REAR GATE	FIG-622 63264	1	X 21.60
59122SG060	MUD GUARD, REAR RIGHT	FIG-541 59112	1	X 57.60
59122SG070	MUD GUARD, REAR LEFT	FIG-541 59112A	1	? X 57.60
63516SG001	WEATHER STRIP-REAR GATE	FIG-901 63516	1	X 111.60
94026SG000VH	TRIM PANEL-REAR SKIRT	FIG-940 94046	1	X 36.00
57704SG012	BUMPER-FACE, REAR	FIG-591 57704A	1	de ✓ 540.00 ✓
57711SG0219P	BACK BEAM COMPLETE-REAR	FIG-591 57711D	1	nn X 288.00
57707SG080	BRACKET-REAR BUMPER SIDE, RIGHT	FIG-591 57707H	1	nn X 14.40
57707SG090	BRACKET-REAR BUMPER SIDE, LEFT	FIG-591 57707I	1	nn ✓ 14.40 ✓
57707SG060	BRACKET-REAR BUMPER CORNER, RIGHT	FIG-591 57707AC	1	nn X 18.00
57707SG070	BRACKET-REAR BUMPER CORNER, LEFT	FIG-591 57707AD	1	nn ✓ 18.00 ✓
Page-Total				3,213.00

Memo

Grand Total
3,640.80

--

Tel

Estimate

Date 03 / 03 / 2021

002 / 002

Name	QUOTATION FOR SBW54A	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG112545

Part Number	Part Code Name	Part Code	Q'ty	Price
57731SG010NN	COVER-REAR BUMPER	FIG-591 57731C	1	12.60
57731SG060	COVER-REAR BUMPER	FIG-591 57731CA	1	14.40
84281SC000	REFLEX REFLECTOR ASSEMBLY-RIGHT	FIG-842 84281	1	20.40
84281SC010	REFLEX REFLECTOR ASSEMBLY-LEFT	FIG-842 84281A	1	20.40
91111SG000	GARNISH ASSEMBLY-REAR GATE, B	FIG-914 91111P	1	144.00
91713SG000	PROTECTOR-REAR GARNISH	FIG-914 91713	1	21.60
91713SG010	PROTECTOR-REAR GARNISH	FIG-914 91713C	2	10.80
93033SG001	ORNAMENT	FIG-914 93033D	1	79.20
93079SG000	LETTER MARK-REAR	FIG-919 93073Y	1	39.60
93079SG030	LETTER MARK-REAR	FIG-919 93073Y	1	64.80
		Page-Total		427.80
		Sub-Total		3,640.80
		Total		3,640.80
		Tax		0.00
		Grand Total		3,640.80

Memo

Grand Total
3,640.80

--

Tel
