



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2107777

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 11/11/2021
Reference CC4/LPC21002904/Kpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SME 1588J
Insured Veh. YP 4201E
Claim No. 20/21/21/VC00/024287
Policy No. Z/20/VC00/108523
Accident Date 02/03/2021
Inspection Date 08/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21002904/Kpa3q2 Date: 11/11/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 4201E	Veh. Inspected	SME 1588J	
Policy No.	Z/20/VC00/108523	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024287	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	03/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 216I (A)	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBA2X92040VD11374	Colour	METALLIC GREY	
Odometer	35191 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	BRIDGESTONE	4 mm	
L/H Front Tyre	205/55 R17	BRIDGESTONE	4 mm	
R/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/03/2021	Inspection Date	08/03/2021	
Survey held at	TROPICAL TECH AUTOMOBILE SERVICES BLK 5032, ANG MO KIO AVENUE 3 #01-303 IND. PARK 2 SINGAPORE 569535			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 1588J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR GLASS	SERVICEABLE	750.00	-
1	FRONT RH DOOR PILLAR CHROME (TOP)	DENTED	195.00	195.00
1	REAR RH DOOR	BENT	1,809.00	1,150.00
1	REAR RH DOOR OUTER HANDLE SEAL	SERVICEABLE	45.00	-
1	REAR RH DOOR SOUND INSULATION	NECESSARY	255.00	255.00
1	REAR RH FENDER	BENT	4,273.00	1,675.00
1	REAR RH FENDER COWLING	SERVICEABLE	280.00	-
1	RH TAIL LAMP	SERVICEABLE	750.00	-
1	REAR BUMPER	CRACKED	2,098.00	1,245.45
1	REAR BUMPER SIDE BRACKET (RH)	DISTORTED	109.00	109.00
1	REAR RH SPORT RIM	DENTED	1,728.00	1,108.00
1	FUEL LIP COVER (OUTER)	TO REPAIR SEE LABOUR	180.00	-
	LESS 10% DISCOUNT		-1,247.20	-573.75
			11,224.80	5,163.70
	<u>LABOUR</u>			
	REMOVE AND TRANSFER REAR RH DOOR NECESSARY ATTACHMENT SPART PART ITEMS. INCLUSIVE OF THE REPAIR OF FUEL LIP COVER (OUTER).}		1,200.00	800.00
	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS.}		-	-
	REMOVE AND REFIT FRONT RH DOOR GLASS ,RH DOOR PILLAR CHROME (TOP,REAR RH DOOR,REAR RH DOOR OUTER HANDLE SEAL ,REAR RH DOOR SOUND INSULATION,REAR RH FENDER COWLING ,REAR BUMPER ,REAR BUMPER SIDE BRACKET (RH),REAR RH SPORT RIM ,FUEL TIP COVER (OUTER) }		-	-
	HEAT/WELD /PANEL BEATING ,ROOF TOP ,REAR RH FENDER		-	-
	,HEAT/WELD/BEARING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK.}			
	TUFF KOTE REAR DAMAGED PORTION.		150.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PUTTY /PRIMER APPLICATION ,SPRAY PAINTING ON ROOF TOP ,REAR RH DOOR ,RH SIDE SKIRT,REAR RH FENDER ,REAR BUMPER ,FUEL LIP COVER (OUTER).		1,200.00	900.00
			2,550.00	1,760.00
GRAND TOTAL			13,774.80	6,923.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CC4/LPC21002904/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 1588J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 1588J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 1588J

RE-INSPECTION

