

REF: LPL/21002904/K

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535
Tel 6481 7773 / 6481 1403 Fax 6484 4978
E-mail: tasc303@singnet.com.sg

M/s: **Lonpac Insurance Bhd**
300 Beach Road,
#17-04/07 The Concourse
Singapore 199555

Attn: Attention: Motor Claims Third Party Department
Tel: Tel: 62507388
Fax: Fax: 62963767

Estimate bill: TT 10 / 21 / TP / WT

Registration No: SME1588J

Make model: BMW 216i

WBA2X92040VD11374

Date: 04 / 03 / 2021

Mileage:

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YP4201E AND SME1588J
ALONG KRANJI WAY ON 02 MARCH 2021 AT ABOUT 0730 HRS.

lpc	Front RH door glass	\$	750.00	X
lpc	Front RH door pillar chrome (Top)	\$	195.00	—
lpc	Rear RH door → 1150	\$	1,809.00	—
lpc	Rear RH door outer handle seal	\$	45.00	X
lpc	Rear RH door sound insulation	\$	255.00	—
lpc	Rear RH fender → 1675	\$	4,273.00	—
lpc	Rear RH fender cowl	\$	280.00	X
lpc	RH tail lamp	\$	750.00	X
lpc	Rear bumper 1245.45	\$	2,098.00	—
lpc	Rear bumper side bracket (RH)	\$	109.00	—
lpc	Rear RH sport rim 1108	\$	1,728.00	—
lpc	Fuel lip cover (Outer)	\$	180.00	X
	Sub A total:	\$	12,472.00	
	Less 10% discount:	\$	1,247.20	
	A total:	\$	11,224.80	
		\$	11,224.80	

Total amount of Page 1:

Not Notified
Resurvey B4pain

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7 days
L1Rm \$5300h

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

S : **Lonpac Insurance Bhd**
300 Beach Road,
#17-04/07 The Concourse
Singapore 199555

Estimate billl : TT 10 / 21 / TP / WT

Registration No : SME1588J

Attention : Motor Claims Third Party Department
Tel : 62507388
Fax : 62963767

Make model : BMW 216i

Page :

Date : 04 / 03 / 2021

**AFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YP4201E AND SME1588J
ONG KRANJI WAY ON 02 MARCH 2021 AT ABOUT 0730 HRS.**

Remove and transfer rear RH door necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit front RH door glass, RH door pillar chrome (Top), rear RH door,
rear RH door outer handle seal, rear RH door sound insulation, rear RH fender
cowling, rear bumper, rear bumper side bracket (RH), rear RH sport rim, fuel lip
cover (Outer).

Heat /weld / panel beating roof top, rear RH fender, heat /weld / beating / pull /
straighten / align rear chassis frame by Chassis Alignment jack.

Tuff kote rear damaged portion.

Putty / primer application, spray painting on roof top, rear RH door, RH side skirt,
rear RH fender, rear bumper, fuel lip cover (Outer)

Balance amount brought from Page 1 :

Grand final amount :

\$ 1,200.00 *8001*

\$ 150.00 *601*

\$ 1,200.00 *9001*

\$ 11,224.80

\$ 13,774.80

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



☐ Weekend (\$) Others