

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-Mar-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6814 T

1 pc	Front o/s head lamp	\$	1,028.00 X
1 pc	Front bumper	\$	531.00 RY
1 pc	Front bumper emblem	\$	44.00 X
1 pc	Front bumper o/s side retainer	\$	16.00 X
1 pc	Front o/s wheel cover	\$	116.00 X
1 pc	Front bumper o/s protector	\$	51.00 X
1 pc	Front bumper o/s fog lamp cover	\$	66.00 X
1 pc	Front o/s fender	\$	384.00 RY
1 pc	Front o/s fender inner shield	\$	120.00 X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

\$ 1,328.00
\$ 132.80
\$ 1,195.20

S/NETT

1 pc	Front bumper clips	\$	48.00 X
1 pc	Front o/s fender sticker	\$	30.00 RY
1 set	Front o/s fender inner shield clips	\$	28.00 X

Acknowledged by Repairer

Signature:

Date:

Sundry	\$	50.00 20.
To adjust front o/s head lamp	\$	40.00 X
To check front o/s wheel alignment	\$	80.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	200. 600.00
To putty and spray painting on front bumper, front o/s fender,	\$	400.00 ✓
To apply rustproofing on the repaired and replaced panels.	\$	80.00 X
	\$	2,551.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Tauhin 9749 5719
WP 10/3/21 R 1630
Rising after repair.
2 days
tauhin@khamf.com