

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SLU9761A [YOUR INSURED] & SKA8182U [OUR CLIENT]
ON 03/03/2021.

ESTIMATED REPAIR COSTS FOR SKA8182U

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BOOTLID <i>Buc</i>	\$ 2,127.00	✓ 1735.00
1PC	BOOTLID LOGO <i>Hec</i>	\$ 74.00	✓
1PC	BOOTLID 'CGI' EMBLEM <i>Hec</i>	\$ 101.00	✓ 45.00
1PC	BOOTLID 'C180' EMBLEM <i>Hec</i>	\$ 85.00	✓
1PC	BOOTLID 'C&C' EMBLEM <i>Hec</i>	\$ 100.00	✓ 85.20
1PC	BOOTLID CENTER CHROME <i>2 broken mirror</i>	\$ 436.00	✓ 365.00
2PCS	BOOTLID NO. PLATE LAMP L+R @ \$98.00 EACH <i>HU</i>	\$ 196.00	X
1PC	BOOTLID INNER TRIM <i>2 defunct 1st</i>	\$ 563.00	✓ 385.90
1PC	BOOTLID WEATHER STRIP <i>defunct</i>	\$ 399.00	✓ 197.50
2PCS	BOOTLID HINGE L+R @ \$174.00 EACH <i>2 1st</i>	\$ 348.00	✓
2PCS	BOOTLID HINGE GARNISH L+R @ \$149.00 EACH <i>SVZ</i>	\$ 298.00	X
1PC	BOOTLID LOCK <i>Dam</i>	\$ 349.00	✓
1PC	BOOTLID SWITCH <i>HU</i>	\$ 298.00	X
1PC	REAR WINDSCREEN MOULDING <i>Hec</i>	\$ 349.00	✓ 168.50
1PC	REAR BUMPER <i>Buc 1st</i>	\$ 1,797.00	✓ 1312.00
2PCS	REAR BUMPER SIDE RETAINER L+R @ \$96.00 EACH <i>HU</i>	\$ 192.00	X
1PC	REAR BUMPER CENTER CHROME <i>broken</i>	\$ 417.00	✓ 120.00
2PCS	REAR BUMPER SIDE CHROME L+R @ \$254.00 EACH <i>broken Hec</i>	\$ 508.00	✓ 230.00
1PC	REAR BUMPER CENTER BRACKET <i>broken 1st</i>	\$ 330.00	✓
2PCS	REAR BUMPER SIDE BRACKET L+R @ \$173.00 EACH <i>HU</i>	\$ 346.00	X ✓ 140.00
1PC	REAR BUMPER UNDER COVER CENTER <i>HU</i>	\$ 410.00	X
2PCS	REAR BUMPER UNDER COVER SIDE L+R @ \$239.00 EACH	\$ 478.00	X
1PC	REAR REINFORCEMENT BAR <i>Buc HU</i>	\$ 1,506.00	✓ 615.00
1PC	REAR BUMPER TOW HOOK COVER <i>dislodged</i>	\$ 79.00	✓
2PC	TAIL LAMP L+R @ \$881.00 EACH <i>broken 542.00 x 2</i>	\$ 1,762.00	✓ 1084.00
2PC	TAIL LAMP PANEL L+R @ \$479.00 EACH <i>Dental</i>	\$ 958.00	✓ 770.00
2PC	TAIL LAMP LOWER BRACKET L+R @ \$184.00 EACH <i>HU</i>	\$ 368.00	X
2PC	REAR FENDER L+R @ \$2,794.00 EACH <i>Dental 2241.20 x 2</i>	\$ 5,588.00	✓ 4482.40
2PCS	REAR FENDER OUTER GARNISH L+R @ \$301.00 EACH <i>broken</i>	\$ 602.00	✓ 300.00
1PC	REAR FENDER INNER PANEL LH <i>1st</i>	\$ 1,789.00	X

620.00

2PC	REAR FENDER INNER TRIM L+R @ \$946.00 EACH 2 set	\$ 1,892.00	2 ✓ 1240.00
2PC	REAR FENDER INNER SHIELD L+R @ \$182.00 EACH HU	\$ 364.00	X
1PC	REAR FENDER AIR DUCT LH broken / broken	\$ 101.00	2 ✓
1PC	REAR WHEEL HOUSING LH 2 set	\$ 1,829.00	X
1PC	REAR END PANEL broken	\$ 1,558.00	✓ 1084.00
1PC	REAR END PANEL TOP GARNISH 2 broken	\$ 463.00	2 ✓ 197.00
1PC	SPARE WHEEL PANEL broken	\$ 2,421.00	✓ 449.00
2PC	SPARE WHEEL QUARTER PANEL L+R @ \$776.00 EACH 2	\$ 1,552.00	2 X
1PC	SPARE WHEEL PANEL TOP BOARD 1st / broken	\$ 569.00	✓ 355.32
1PC	SPARE WHEEL PANEL TOOL BOX HU	\$ 492.00	X
1PC	REAR EXHAUST PIPE HU	\$ 2,227.00	X
1PC	REAR EXHAUST MUFFLER 2 set	\$ 980.00	2 ✓
1PC	REAR EXHAUST HEAT SHIELD 2 check / broken 1st	\$ 226.00	2 ✓ 184.30
1PC	REAR EXHAUST MOUNTING 2 HU	\$ 101.00	2 X
1PC	DRIVER SEAT BELT broken	\$ 1,680.00	✓ 650.00
1PC	FRONT PASSENGER SEAT BELT broken	\$ 1,671.00	✓ 650.00
1PC	DRIVER SEAT BELT BUCKLE broken	\$ 560.00	X
1PC	FRONT PASSENGER SEAT BELT BUCKLE broken	\$ 560.00	X
2PCS	REAR SEAT BELT LH / RH @ \$1,570.00 EACH broken	\$ 3,140.00	✓ 930.00
1PC	DRIVER HEAD REST AIR BAG broken / broken	\$ 1,829.00	✓ 788.00
1PC	FRONT PASSENGER HEAD REST AIR BAG broken / broken	\$ 1,789.00	✓ 788.00
1PC	SRS CONTROL MODULE broken / broken	\$ 1,882.00	✓ 1050.00

1PC SPARE WHEEL PANEL TOP BOARD INNER PARTS SUM: \$ 50,739.00
 broken & 380.00 ✓ PARTS LESS 10%: \$ 5,073.90
 PARTS TOTAL: \$ 45,665.10

23127.12
 1070 20814.40
 =

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE & CASING HU	\$ 100.00	X
*	TO SUPPLY 1 SET REAR REVERSE SENSOR broken	\$ 300.00	250/-
*	TO SUPPLY REAR WINDSCREEN SEALANT broken	\$ 80.00	40/-
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL HU	\$ 30.00	X
*	TO SUPPLY BOOTLID INNER TRIM CLIPS broken	\$ 50.00	15/-
*	TO SUPPLY BOOTLID CENTER CHROME CLIPS broken HU	\$ 50.00	X 15/-
*	TO SUPPLY REAR BUMPER CLIPS broken	\$ 50.00	20/-
*	TO SUPPLY REAR BUMPER CHROME CLIPS HU	\$ 50.00	X
*	TO SUPPLY REAR BUMPER UNDER COVER CLIPS HU	\$ 50.00	X
*	TO SUPPLY REAR END PANEL SEALANT broken	\$ 80.00	20/-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS broken	\$ 50.00	15/-
*	TO SUPPLY SPARE WHEEL PANEL SEALANT broken	\$ 80.00	20/-
*	TO SUPPLY REAR WHEEL HOUSING SEALANT HU	\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT broken	\$ 80.00	20/-
*	TO SUPPLY REAR FENDER INNER PANEL SEALANT HU	\$ 80.00	X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS broken	\$ 50.00	20/-
*	TO SUPPLY REAR FENDER INNER SHIELD CLIPS HU	\$ 80.00	X
*	TO SUPPLY REAR FENDER OUTER GARNISH CLIPS HU	\$ 50.00	X
*	TO SUPPLY TAIL LAMP CLIPS HU	\$ 50.00	X
*	TO SUPPLY REVERSE CAMERA HU	\$ 800.00	X

435.00
 =

- * TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILL \$ ~~400.00~~ 120/-
REPAIRS
- * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & \$ ~~2,400.00~~ 1800/-
- * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ ~~2,400.00~~ 1400/-
- * TO TUFF COAT DAMAGED AREAS \$ ~~300.00~~ 40/-
- * TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS \$ ~~500.00~~ 120/-
- * TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS \$ ~~200.00~~ 60/-
- * TO RNR REVERSE CAMERA TO FACILITATE REPAIRS \$ ~~120.00~~ 20/-
- * TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS \$ ~~120.00~~ 40/-
- * TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE R \$ ~~200.00~~ 60/-
- * TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS \$ 100.00 40 4020.00
- * TO RNR ALL AFFECTED SEAT BELTS TO FACILITATE REPAIR \$ ~~300.00~~ 120/-
- * TO RNR DASHBOARD ASSY TO FACILITATE REPAIRS \$ ~~600.00~~ NN
- * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ ~~200.00~~ 30/-
- * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UN \$ ~~1,000.00~~ 180/-
ALL MEMORIES TO FACTORY DEFAULT SETTINGS

LABOUR & S/N TOTAL: \$ 11,080.00

TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 56,745.10

03/03/2021 @ 1700hrs
Hut Andrew
1/sum 12 day.

1 Jan

2KK Auto

Chuk P. Mies

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: