

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

YVIMV28H0H23 89920

ANG SOON HENG
BLK 414 TAMPINES STREET 41
#09-317
S 520414

TPA x A.
Cecilia

Vehicle No : SLJ 8774 C
Make/Model : VOLVO V40
Accident date : 03.03.2021

No	DESCRIPTION	Qty	Amount (\$)
List Items			
1	Rear bumper <i>Debond</i>	1	\$ 2,200.00 <i>1766</i>
2	Rear bumper side holder @ \$71.50 <i>new</i>	2	\$ 143.00
3	Rear bumper lower lip <i>Debond</i>	1	\$ 935.00 <i>522</i>
4	Rear bumper reflector @ \$99.00 <i>RAH ut</i>	2	\$ 198.00 <i>98</i>
5	Rear bumper towing hook cover <i>Debond</i>	1	\$ 55.00 ✓
6	Rear bumper reinforcement <i>Dented</i>	1	\$ 990.00 ✓
7	Rear bumper bracket @ \$104.50 <i>holer</i>	2	\$ 209.00 ✓
8	Rear bumper sponge <i>new</i>	1	\$ 93.50 ✓
9	Rear number plate lamp @ \$55.00 <i>new</i>	2	\$ 110.00 ✓
10	Rear end panel <i>Repair</i>	1	\$ 748.00 ✓
11	Front bumper <i>Debond</i>	1	\$ 2,310.00 <i>1850</i>
12	Front bumper side holder @ \$82.50 <i>new</i>	2	\$ 165.00 ✓
13	Front bumper lower centre grille <i>3 new</i>	1	\$ 132.00 ✓
14	Front bumper lower side grille @ \$198.00 <i>new</i>	2	\$ 396.00 ✓
15	Front bumper reinforcement <i>Dented</i>	1	\$ 760.00 ✓
16	Front bumper sponge <i>crushed</i>	1	\$ 231.00 ✓
17	Front bumper reinforcement garnish <i>Debond</i>	1	\$ 181.50 ✓
18	Front grille <i>ut</i>	1	\$ 418.00 ✓
19	Front grille emblem <i>new</i>	1	\$ 88.00 ✓
20	Front headlamp @ \$2,090.00 <i>LH crushed</i>	2	\$ 4,180.00 <i>2090</i>
Total			\$ 14,543.00
Special Nett Items			
1	Front number plate <i>Dented</i>	1	\$ 50.00 <i>30</i>
2	Front number plate holder <i>Debond</i>	1	\$ 50.00 <i>30</i>
3	Front bumper clips (1 set) <i>new</i>	1	\$ 60.00 <i>30</i>
4	Rear bumper reverse sensor @ \$198.00 <i>2 pieces dented</i>	4	\$ 792.00 <i>396</i>
5	Rear number plate <i>Dented</i>	1	\$ 50.00 <i>30</i>
6	Rear number plate holder <i>ut</i>	1	\$ 50.00 <i>30</i>
7	Rear bumper clips (1 set) <i>new</i>	1	\$ 60.00 <i>30</i>
Total			\$ 100.00

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ANG SOON HENG
BLK 414 TAMPINES STREET 41
#09-317
S 520414

Vehicle No :SLJ 8774 C
Make/Model :VOLVO V40
Accident date :03.03.2021

No	DESCRIPTION	Qty	Amount (S\$)
Labour Cost			
1	Remove & reinstall air con		\$ 150.00
2	Remove & reinstall bootlid garnish		\$ 150.00
3	Remove & reinstall reverse sensor		\$ 200.00
4	Remove ,replace & repair consistent to the accident	1770	\$ 1,500.00
5	Respray painting		\$ 1,400.00
6	Tuff kote		\$ 150.00
Total			\$ 3,550.00
Grand Total			\$ 18,193.00

total: 10778.65

4/3 : 88K

07 Days.

8K 88K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: