



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS3/III19017409/Evf3e2-1 Date: 09/03/2021 Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8964E	Veh. Inspected	GBH 9360K
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19100016/01	Excess (\$)	0.00
Assign From	CARINE KEK PHER SER	Assign Date	04/03/2021
2. Vehicle Particulars & Condition			
Make & Model	ISUZU NHR69E	c.c	3059
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JAANHR69E57100091	Colour	BLUE
Odometer	681705 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14C	BRIDGESTONE	5 mm
L/H Front Tyre	185 R14C	BRIDGESTONE	5 mm
R/H Rear Tyre	185 R14C (D)	APLUS	5/5 mm
L/H Rear Tyre	185 R14C (D)	APLUS	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/10/2019	Inspection Date	14/10/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	