

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002936/KBA3Q2

Date: 24/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMQ191M

Insured Vehicle No : GBC6563M

Date of Loss: 01/03/2021

Nature of Claim: TP

Claim No: 9515307189SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ191M**

Make & Model: HONDA FREED, 1.5 G (A)

Engine No: L15B4466539

Reg. Date: 25/10/2019 (Man. Year: 2019)

Chassis No: GB51122322

Colour: Metallic Grey

Odometer: 39567 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 4 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,028.44	2,452.60	575.84	19.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	530.00	370.00	41.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	3,928.44	2,982.60	945.84	24.08
Approved Total (Overridden) (\$)		2,350.00		
(\$)	3,928.44	2,350.00	1,578.44	40.18
+ GST 7.00/7.00% (\$)	274.99	164.50	110.49	40.18
Nett Amount (\$)	4,203.43	2,514.50	1,688.93	40.18
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 04/03/2021

Date Inspected: 08/03/2021 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOCK	Repair	153.20 FL	*- FL
2	1		*FRONT GRILLE ASSY	Cracked	580.00 FL	*580.00 FL
3	1		*HEADLAMP RH	Cut	1,350.00 FL	*1,350.00 FL
4	1		*HEADLAMP LOWER BEAM RH	Repair	36.50 FL	*- FL
5	1		*FRONT BUMPER	Buckled	1,050.00 FL	*1,050.00 FL
6	1		*FRONT BUMPER TOW COVER	*Check	15.40 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Serviceable	165.00 FL	*- FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	19.50 FL	*- FL
9	12		*FRONT BUMPER CLIPS	Necessary	42.00 FL	*42.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	*Check	295.00 FL	*- FL
11	1		*AIR GUIDE RH	*Check	35.20 FL	*- FL
12	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,776.80	3,057.00
- List Item Discount on L Items 20.00/20.00% (S\$)	748.36	604.40
Total Parts (S\$)	3,028.44	2,452.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO ARRANGE ,SUPPLY AND SEAL OFF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY	New	60.00	60.00
3	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD ,TO KNOCK & REPAIR FRONT BONNET ,FRONT INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	400.00	250.00
4	TO SPRAY FRONT BONNET ,FRONT BUMPER	New	400.00	200.00
Gross Labour Cost (\$\$)			900.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >