

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : RAZALI BIN MASUDI
 483 ADMIRALTY LINK
 #02-21
 SINGAPORE 750483

ATTN:

Your Ref No: SMQ191M
 Claim Type: Third Party → MG
 Accident Date: 01/03/2021
 TP Veh Reg No: GBC6563M

Estimate No: MC1901794
 Date: 03 Mar 2021
 Policy No: GA508474
 Veh Reg No: SMQ191M
 Make/Model: HONDA FREED 1.5G
 CVT

Not Withheld
 Recovery B4 point

2 days

Estimate Repair Cost to Vehicle No :SMQ191M

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BONNET LOCK	1 PC	153.20	X
2 FRONT GRILLE ASSY	1 PC	580.00	✓
3 HEADLAMP RH	1 PC	1,350.00	✓
4 HEADLAMP LOWER BEAM RH	1 PC	36.50	X
5 FRONT BUMPER	1 PC	1,050.00	✓
6 FRONT BUMPER TOW COVER	1 PC	15.40	?
7 FRONT BUMPER LOWER GRILLE	1 PC	165.00	X
8 FRONT BUMPER SIDE RETAINER RH	1 PC	19.50	X
9 FRONT BUMPER CLIPS	12 PC	42.00	✓
10 FRONT BUMPER REINFORCEMENT	1 PC	295.00	?
11 AIR GUIDE RH	1 PC	35.20	?
		3,741.80	
	Less 20%	748.36	2,993.44
Special Nett			
12 NUMBER PLATE	1 PC	35.00	✓
		35.00	35.00
LABOUR			
13 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
14 TO ARRANGE, SUPPLY AND SEAL OFF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY.	1 PC	60.00	✓
15 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT BONNET, FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	2501
16 TO SPRAY FRONT BONNET, FRONT BUMPER.	1 PC	400.00	2001
		900.00	900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

