

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 04.03.2021

Time: 15:30:52

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305456970
 REGN NO : SHD3526P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 04.03.2021 12:45
 ACCIDENT DATE : 04.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00	19.44	ref	✓
0002 04-01-0104-2271-G	EMBLEM-IONIQ	1	31.30	20.00	25.04	ref	✓
0003 28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	2.00-	30.00	ref	✓
0004 28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1 N	30.00	0.20	30.00	ref	✓
0005 28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1 N	40.00	0.02-	40.00	ref	✓
0006 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	de	✓
0007 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	de	✓
0008 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	X ref	✓
0009 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	ref	✓
0010 04-01-0104-2256-G	PANEL ASSY-TAIL GATE#	1	2,480.40	20.00	1,984.32	bt	✓
0011 04-01-0104-2175-G	SYMBOL MARK-II	1	28.00	20.00	22.40	ref	✓
0012 FNPS	NUMBER PLATE FRONT	1 N	25.00	2.00-	25.00	ref	✓
0013 09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40	ref	✓

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305456970
 REGN NO : SHD3526P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 04.03.2021 12:4
 ACCIDENT DATE : 04.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 04-01-0104-2370-G LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	int ✓
0015 05-01-0199-0032-A WINDSCREEN AHESIVE-310MLC	2 N	46.00	2.00-	46.00	net ✓
					SUB-TOTAL : 3,211.92

JOB NATURE

0000 PB	PANEL BEATING	1100.00	525
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 L	RENEW REAR WINDSCREEN GLASS	120.00	✓
0003 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
0004 17-01	CHECK ALL LIGHTING	50.00	30 1205

SUB-TOTAL : 1,950.00

Tanpin 97415749
 WP' 4/3/21E Spru
 4/3 Resurvey after repair
 03 days
 Tanpin @ theAuto.com

Davanti 4302.28
 4513400
 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: