



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102984

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 29/04/2021
Reference CC3/CTI21002957/T1es3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 4323B
Insured Veh. XD 3345E
Claim No. SNM21D201186/C02
Policy No. DMCVSNW00112172002
Accident Date 01/03/2021
Inspection Date 02/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21002957/T1es3q2 Date: 29/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 3345E	Veh. Inspected	SHD 4323B	
Policy No.	DMCVSNW00112172002	Coverage (\$)	0.00	
Claim No.	SNM21D201186/C02	Excess (\$)	0.00	
Assign From		Assign Date	02/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU103089820	Colour	BLUE	
Odometer	168860 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2021	Inspection Date	02/03/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4323B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	TO REPAIR SEE LABOUR	889.70	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER UNDER COVER	TO REPAIR SEE LABOUR	552.60	-
2	REAR BUMPER SIDE RETAINER LH/RH @\$112.70	NOT NECESSARY	225.40	-
1	REAR BUMPER UNDER COVER CENTRE	NOT NECESSARY	232.00	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	82.70	-
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
	LESS 25% DISCOUNT		-736.98	-41.53
			2,210.92	124.57
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TRUNK LID ASSP STICKER (SN)	CUT	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			285.70	100.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE,REAR BUMPER AND REAR BUMPER UNDER COVER .		780.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.	NOT NECESSARY	60.00	-
	TUFF KOTE.	NOT NECESSARY	90.00	-

Report Ref No. CC3/CTI21002957/T1es3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REVERSE SENSOR .		60.00	30.00
			1,590.00	880.00
GRAND TOTAL			4,086.62	1,104.57
RECOMMENDED COST OF REPAIRS				1,104.57

Report Ref No. CC3/CTI21002957/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4323B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4323B

RE-INSPECTION

