

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHD4323B

Make : TOYOTA

Model : PRIUS

DOA : 3/1/2021

Date :

Insurance: CHINA

MVA : CHIANG

Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount	
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70	Ry
1	REAR TRUNK LID LOGO (PRIUS)			\$60.80	net
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40	net
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90	net
1	REAR BUMPER			\$458.60	Ry
1	REAR BUMPER UNDER COVER			\$552.60	Ry
1	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40	X
1	REAR BUMPER UNDER COVER CENTRE			\$232.00	X
1	REAR BUMPER TOWING COVER			\$82.70	X
10	REAR BUMPER CLIPS			\$22.00	X
1	REAR BUMPER REINFORCEMENT			\$318.80	X
SUB TOTAL				\$2,947.90	
LESS 25%				\$736.98	
DISCOUNTED TOTAL				\$2,210.93	
1	REAR TRUNK LID APPS STICKER			\$40.00	cut Net
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00	net Net
1	REAR BUMPER MAT			\$50.00	X Net
1	REAR BUMPER REVERSE SENSOR			\$135.70	? Net
				\$285.70	
Labour Charge					
	Panel Beating			\$780.00	350
	Spray Painting Charge			\$600.00	500
	Wiring Charge			\$60.00	X
	Tuff Kote			\$90.00	X
	Remove/Refix Reverse Sensor			\$60.00	30
TOTAL LABOUR				\$1,590.00	
ESTIMATE TOTAL				\$4,086.63	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphn 97415749 WP' 2/3/24 @ 5pm 11:30 AM
 P/p Resurvey after repair 02 days
 Tanphn @ 11:30 AM

Date/Time: 02.03.2021 08:34

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305456364

CUSTOMER

R/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)
(P)


SCOUT CARD NO.

REGN NO.: SHD4323B	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4A01	DATE/TIME IN 01.03.2021 14:40
YR OF MANU. 05.12.2019	TARGET DATE
CHASSIS CODE JTDKB3FU103089820	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 01.03.2021
NATURE: 3P 01.03.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

By:

Vehicle No.:

Vehicle No.:

Vehicle No.: **SHD4323B**

CHIANG

SHD4323B

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard