

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
Tel : 91082728

TAC Contracts Pte Ltd
20 Ang Mo Kio Industrial Pk 2A
#04-06 Techlink
Singapore 567761

Vehicle No : GX 8600 G
Make/Model : Nissan Cabstar
Year : 2004

Not Notifier
11/12/08 3250h
Putty After Paint
4 days

JNISC2F24Z0855546

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

Nett

1 pc	Front n/s headlamp	473.40	CM	\$588.50	✓
1 pc	Front n/s headlamp lower garnish	155.10	R	\$155.10	✓
1 pc	Front n/s corner panel	392.20	R	\$486.30	✓
1 pc	Front n/s rear view mirror	193.20	RU	\$193.20	✓
1 pc	Front n/s rear view mirror bracket	287.30	R	\$287.30	✓
1 pc	Front n/s rear view mirror bracket cover	152.80	mi	\$152.80	✓
1 pc	Front bumper	954.10	Bul/lot	\$1,155.00	✓
1 pc	Front n/s bumper bracket	105.10	n	\$105.10	×
1 pc	Front radiator grille	578.60	mg	\$675.60	✓
1 pc	Front radiator grille emblem	65.70	nn	\$65.70	×
1 pc	Front o/s step panel	171.20	cm	\$171.20	✓
				\$4,035.80	
				Less 10 %	\$403.58
					\$3,632.22

S Nett

1 pc	Front n/s door black sticker	30	na	\$30.00	✓
------	------------------------------	----	----	---------	---

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.	\$1,000.00	500l
To putty and spray paint on front accident portion.	\$1,000.00	500h
Check & reconnect wiring.	\$30.00	20l
To respray anti-rust proofing treatment	\$120.00	30l

LKK Auto Consultants hence notify Total

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$5,812.22