


**N-51 AUTOMOTIVE PTE LTD**

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

JUST 2 RIDE  
 BLK 36 BEDOK SOUTH AVE 2 #05-399  
 SINGAPORE 460036

Contact : 92984774, 88238966

TP Budget Direct.  
 Xiao Chen

### ESTIMATE

Repair Code : CLM16711

Date in : 24/02/2021

Vehicle Num. : PC3587Z

Model : TOYOTA HIACE COMMUTER GL 3.0 AT 2WD

Chassis/Eng# : KDH22300023283/1KD2496554

### Parts and Labour Assesment

| Description of part                                    | Qty | Unit Price | Amount                  |
|--------------------------------------------------------|-----|------------|-------------------------|
| REAR BUMPER <i>Rehnd</i>                               | 1   | 661.30     | ✓ 661.30                |
| REAR BUMPER SIDE RETAINER LR <i>RH Dayd</i>            | 2   | 66.30      | <del>66.30</del> 132.60 |
| REAR RH FENDER <i>Reis</i>                             | 1   | 1712.45    | X 1,712.45              |
| REAR RH FENDER INNER AIR VENT <i>could</i>             | 1   | 100.45     | ✓ 100.45                |
| REAR RH TAILLAMP <i>could</i>                          | 1   | 354.80     | ✓ 354.80                |
| REAR RH TAILLAMP INNER PANEL <i>Reis</i>               | 1   | 390.95     | X 390.95                |
| REAR RH TAILLAMP LOWER GARNISH <i>could</i>            | 1   | 171.70     | ✓ 171.70                |
| REAR RH TAILLAMP LOWER GARNISH SIDE BRACKET <i>neu</i> | 1   | 53.00      | ✓ 53.00                 |
| Subtotal before discount                               |     |            | 3,577.25                |
| Percentage discount 25%                                |     |            | 894.31                  |
| <b>Sub-total 1</b>                                     |     |            | <b>2,682.94</b>         |
| REAR BUMPER CLIPS - SET <i>neu</i>                     | 1   | 50.00      | <del>30</del> 50.00     |
| REAR RH FENDER WINDSCREEN SEAL <i>3 inner</i>          | 1   | 80.00      | X 80.00                 |
| REAR RH FENDER WINDSCREEN SEALANT                      | 1   | 80.00      | X 80.00                 |
| REAR RH TAILLAMP CLIPS - SET <i>neu</i>                | 1   | 25.00      | <del>10</del> 25.00     |
| REAR RH TAILLAMP LOWER GARNISH CLIPS - SET <i>neu</i>  | 1   | 20.00      | <del>10</del> 20.00     |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*



# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

JUST 2 RIDE

BLK 36 BEDOK SOUTH AVE 2 #05-399

SINGAPORE 460036

Contact : 92984774, 88238966

## ESTIMATE

Repair Code : CLM16711

Date in : 24/02/2021

Vehicle Num. : PC3587Z

Model : TOYOTA HIACE COMMUTER GL 3.0 AT 2WD

Chassis/Eng# : KDH22300023283/1KD2496554

|                          |                 |
|--------------------------|-----------------|
| Subtotal before discount | 255.00          |
| Percentage discount 0%   | 0.00            |
| <b>Sub-total 2</b>       | <b>255.00</b>   |
| <b>Parts-total</b>       | <b>2,937.94</b> |

## LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall fender glass

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

|                      |          |
|----------------------|----------|
| Labour Total         | 2,090.00 |
| Parts & Labour Total | 5,027.94 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.\*\*\*

page 2

Total: 2235.91

4/5 : 1.8k ✓

84 Days