

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SIM YEW THONG
 410C FERNVALE ROAD
 #14-90
 SINGAPORE 793410

Estimate No: MC1901793
 Date: 03 Mar 2021
 Policy No: DMPPHQ20-003735
 Veh Reg No: SLD7946L
 Make/Model: TOYOTA ESTIMA
 AERAS 2.4

ATTN:

Your Ref No: SLD7946L
 Claim Type: Third Party → *ATC*
 Accident Date: 25/02/2021
 TP Veh Reg No: SLZ1648X

*Lick
3pm*

Not Notified

Resurvey B4paim

4-6 days

Estimate Repair Cost to Vehicle No :SLD7946L

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING COMPLETE	1 PC	<i>Ne</i> 101.60	✓
2 TAILGATE	1 PC	<i>B</i> 1,939.50	✓ 1,753.60
3 TAILGATE EMBLEM	1 PC	<i>Ne</i> 59.80	✓
4 TAILGATE ESTIMA LOGO	1 PC	<i>Ne</i> 49.75	✓
5 TAILGATE AERAS LOGO	1 PC	<i>Ne</i> 55.67	✓
6 TAILGATE NO PLATE GARNISH	1 PC	<i>Ne</i> 200.10	X
7 TAILGATE LOCK	1 PC	<i>Ne</i> 490.30	✓
8 TAILGATE RUBBER	1 PC	<i>Nec</i> 371.70	7✓
9 TAILGATE INNER TRIMBOARD	1 PC	<i>Ne</i> 501.70	X
10 REAR BUMPER	1 PC	<i>Bu</i> 622.10	✓
11 REAR BUMPER BRACKET OUTER LH & RH	2 PC	<i>svc</i> 115.40	7X
12 REAR BUMPER BRACKET INNER LH & RH	2 PC	<i>svc</i> 90.80	7X
13 REAR BUMPER CLIPS	12 PC	<i>Ne</i> 50.40	✓
14 REAR BUMPER KEYLESS ANTENNA	1 PC	<i>svc</i> 191.50	7X
15 REAR BUMPER SPONGE LH & RH	2 PC	<i>BT</i> 159.20	7✓
16 REAR END PANEL	1 PC	<i>BT</i> 755.40	7✓
17 REAR END PANEL GARNISH TOP	1 PC	<i>Bu</i> 280.10	✓
18 REAR END PANEL GARNISH BOTTOM	1 PC	<i>Buc</i> 194.20	7✓
19 REAR END PANEL GARNISH CLIPS	5 PC	26.50	7
20 LAST ROW SEAT FRAME RH - CHECK PRICE	1 PC	0.00	7
21 LAST ROW SEAT COVER RH - CHECK PRICE	1 PC	0.00	7
22 LAST ROW CORNER TRIM INNER RH - CHECK PRICE	1 PC	0.00	7
23 LAST ROW CORNER TRIM OUTER RH - CHECK PRICE	1 PC	0.00	7
24 LAST ROW BACKREST COVER RH - CHECK PRICE	1 PC	0.00	7
		6,255.72	
	Less 25%	1,563.93	4,691.79
Special Nett			
25 REVERSE SENSOR	1 SET	200.00	✓ Shorted
26 INNER SEAL	1 PC	<i>Ne</i> 20.00	✓
27 WINDSCREEN SEALANT	1 PC	<i>Ne</i> 40.00	✓
28 NUMBER PLATE	1 PC	<i>B</i> 35.00	✓
		295.00	295.00
LABOUR			
29 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SIM YEW THONG
410C FERNVALE ROAD
#14-90
SINGAPORE 793410

Estimate No: MC1901793
Date: 03 Mar 2021
Policy No: DMPPHQ20-003735
Veh Reg No: SLD7946L
Make/Model: TOYOTA ESTIMA
AERAS 2.4

ATTN:

Your Ref No: SLD7946L
Claim Type: Third Party
Accident Date: 25/02/2021
TP Veh Reg No: SLZ1648X

Estimate Repair Cost to Vehicle No :SLD7946L

Description	Quantity	List Price	Amount
		S\$	S\$
30 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	100
31 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	✓
32 TO DISMANTLE & INSTALL CAMERA	1 PC	60.00	30
33 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	50
34 TO RESET ENGINE TAILGATE	1 PC	350.00	22 X
35 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	7✓
36 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR REAR BOOT,REAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	700.00
37 TO SPRAY TAILGATE,REAR BUMPER,RR END PANEL.	1 PC	800.00	660
		2,490.00	2,490.00
Total			S\$ 7,476.79
Add GST @ 7%			523.38
Total Amount Payable			S\$ 8,000.17

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND AND CENTS SEVENTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: