

Mu. Asher

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

Email: soonosanmotor@gmail.com

To: Motor Claims Dept

QBE INSURANCE (S,pore) PTE LTD

1, Raffles Quay #29-10

South tower S,pore 048583

Accident date:03/03/2021

Date:04/03/2021

Estimate cost to repair vel: SMA 8952R (Honda Shuttle) claim under vel: SKR 3579C.

Not Asher
Mu
Tel: 62583581

2/c # 78001
5/3/21

8 days

Thru the After rep -

1pce tail gate	1131.10	\$ 1,393.00	1005.00 ✓
1pce tail gate rubber	161.90	170.00	170.00 ✓
2pcs tail gate reflectors@\$340.80	305.20	681.60	0.00 ✓
1pce tail gate emblem		38.00	1.00 ✓
1pce tail gate shuttle plate	48.00	65.00	1.00 ✓
1pce tail gate hybrid plate	52.00	80.10	1.00 ✓
1pce tail gate top chrome cover	281.20	383.10	2.00 ✓
1pce tail gate top lock		167.10	2.00 ✓
1pce tail gate lower lock		115.00	1.00 X
1pce tail gate centre lock switch		175.50	1.00 X
1pce tail gate trime cover	243.80	380.00	2.00 ✓
2pcs tail gate dampers@\$185		370.00	1.00 X
1pce tail gate windscreen rubber	121.60	130.00	1.00 ✓
1set tail gate windscreen tape from		48.00	1.00 ✓
2pcs tai lamps@\$520.50	435.20	1,041.00	2.00 ✓
1pce rear panel	546.10	660.80	3.00 ✓
1pce rear panel lower lock cover	126.80	165.50	0.00 ✓
1pce rear spare tyer panel		956.00	0.00 X
1set rear spare tyer panel paddling		140.00	1.00 X
2pcs rear fender trime covers@\$455	381.20	910.00	2.00 ✓
1pce rear spare tyer top cover board		165.00	1.00 ✓
1pce rear inner hybrid top cover		350.00	1.00 ✓
1pce rear spare tyer tool holder tray		295.00	1.00 ✓
1pce rear spare tyer tool holder side cover		85.00	0.00 X
1pce rear bumper	936.50	1,180.60	0.00 ✓

6954.50

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

Email: soonosanmotor@gmail.com

To: Motor Claims Dept

QBE INSURANCE (S,pore) PTE LTD

1, Raffles Quay #29-10

South tower S,pore 048583

Accident date:03/03/2021

Date:04/03/2021

Estimate cost to repair vel: SMA 8952R (Honda Shuttle) claim under vel: SKR 3579C.

1pce rear bumper tow cover	\$ 16.80	page2 de ✓
2pcs rear bumper reflectors <i>garnishes</i>	170.00	170 ✓
2pcs rear bumper side holders@\$45	90.00	30 ✓
<i>1set</i> 10pcs rear bumper inner clips@ \$4	40.00	10 ✓
1pce rear bumper lower side cover	45.50	17 X
4pcs rear bumper top side clips@\$10	40.00	17 X
1pce rear exhaust pipe	899.00	12 X
	\$11,446.60	
Less 20%	2,289.32	
	\$ 9,157.28	
1pce rear windscreen sealant	140.00	140 40 s/w
1pce rear windscreen sunx sticker	300.00	17 X
1set rear bumper reverse sensors	400.00	should 200 s/w
To towing	150.00	50 60
To rustproof	100.00	90
To check wiring	50.00	20
To computer reset	200.00	60
1pce rear number plate with cover	100.00	50 40 s/w
To dismantle/renew tail gate	150.00	60
To remove/refit rear windscreen	140.00	120
To dismantle/renew reverse sensors	100.00	50
To dismantle/renew rear exhaust pipe	100.00	17 X
To remove/refit rear interior to effect repair	100.00	80
To remove/refit rear top spoiler	100.00	17 X
To dismantle/renew accident portion	1,800.00	1300
To spare paint	1,800.00	1200
TOTAL:	\$14,887.28	

2980

P- 8138.40

20%

P- 6510.72

S-N- 280.00

L- 3040

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

QBE INSURANCE (S,pore) PTE LTD

1, Raffles Quay #29-10

South Tower S,pore 048583

Accident date:03/03/2021

Date;05/03/2021

Estimate cost to repair vel: SMA 8952R (Honda Shuttle) claims under vel: SKR 3579C.

[illegible]

LKK Auto Consultants hence notify
the Repairer of the following:

Acknowledged by Repairer

9830.72
2864.

No: G 13358



迅速拖車服務

SPEEDWAY RECOVERY SERVICE

Reg No: 52977287 J

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

Date: _____

$$3 \overline{) 32}$$

Name/Company

505 505 (N T

Vehicle No SMA 8952 R

Model

From Geylang bharu rd

To
3006 vbj #01-390

Remarks

Time:

Amount

50

OTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed

Ym 5128 T

24 HRS TOWING SERVICE
6841 0080

w Truck

www.speedwayrecovery.com

Email: speedwaytowing@gmail.com

Received By