

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 01/03/2021
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLR2481U
CHASSIS NO: NHP1707060128
MAKE / MODEL: Toyota Sienta 1.5G A
DATE OF ACCIDENT: 27 Feb 2021
YOUR INSURED VEHICLE NUMBER: SLT8872A
MILEAGE: 293420 km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	Rear tailgate / DO	1PC	\$ 1,470.00	\$ 1,470.00 1,180
2	Rear tailgate weatherstrip / CEU	1PC	\$ 360.00	\$ 360.00
3	Rear tailgate lock assy / JWH	1PC	\$ 504.00	\$ 504.00 412
4	Rear tailgate lock catch X SVC	1PC	\$ 64.80	\$ 64.80 X
5	Rear tailgate center garnish holder X R	1PC	\$ 342.00	\$ 342.00 X
6	Rear tailgate Toyota logo / NEC	1PC	\$ 60.00	\$ 60.00 /
7	Rear tailgate Hybride emblem / NEC	1PC	\$ 86.00	\$ 86.00 /
8	Rear end panel X R	1PC	\$ 828.00	\$ 828.00 X
9	Rear end panel top garnish X SVC	1PC	\$ 250.00	\$ 250.00 X
10	Rear bumper cover X R / CRU	1PC	\$ 900.00	\$ 900.00 750
11	Rear bumper LH bracket X SVC	1PC	\$ 90.00	\$ 90.00 X
12	Rear bumper RH bracket X SVC	1PC	\$ 90.00	\$ 90.00 X
13	Rear bumper center black pad / SCR	1PC	\$ 288.00	\$ 288.00 209
14	Rear bumper LH reflector X SVC	1PC	\$ 133.20	\$ 133.20 X
15	Keyless smart buzzer antenna X SVC	1PC	\$ 120.00	\$ 120.00 X
LIST TOTAL S\$:			\$ 5,586.00	3,057
25.00% DISCOUNT S\$:			\$ 1,396.50	-25%
			\$ 4,189.50	2,242.75

SPECIAL NETT			
1	Rear Bumper clips / NEC	1 SET	\$ 80.00 30
2	Reverse sensor X SVC	1 SET	\$ 260.00 300
3	Windscreen sealant / NEC	1PC	\$ 100.00 40
Special Nett Total S\$:			\$ 440.00 70

LABOUR CHARGES			
1	To remove and install rear tailgate glass	\$ 120.00	/
2	Transfer tailgate mechanism, upholstery, seats	\$ 120.00	60
3	To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacemnt of damaged parts. Also include straighttenning of both rear chassis members and floor panel.	\$ 1,250.00	900 600
4	To respray rear tailgate, rear end panel, spare tyre panel, rear bumper, roof top and both rear fenders	\$ 1,000.00	800 500
5	To conduct a standard of opearting procedures post repairs diagnostic scan test as a requirements upon completion of collision repairs	\$ 300.00	X
6	To deactivate and active high voltage battery as a safty precautions	\$300.00	X
TOTAL S\$:		\$ 4,629.50	4,280
7% GST		\$ 324.07	
GRAND TOTAL S\$:		\$ 4,953.57	

Repair day - 3 days

P/P

before paint photo.

Sun Pin(Lkk)

05/03/2021

TP within pre,ulu

2,242.75
70
1,280
3,642.75

PIP
\$ 3,642.75
3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: