

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD604S****AAD2103-017**

*Not Authorized*  
*11 Sep @ 2900h*  
*Repair After Paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**04 MAR 2021****SHD604S**

VF1ABL15AUC283459

RENAULT

LATITUDE

03/03/2021

**CHINA**

30/11/2017

**PART**

- 1 DOOR PANEL REAR RH
- 1 DOOR HINGE UPPER REAR RH
- 1 DOOR HINGE LOWER REAR RH
- 1 DOOR REGULATOR REAR RH
- 1 DOOR REGULATOR MOTOR REAR RH
- 1 DOOR HANDLE OUTER REAR RH
- 1 DOOR HANDLE MODULE REAR RH
- 1 BUMPER COVER REAR
- 1 FENDER PANEL REAR LH

**LIST**

|    |                    |   |
|----|--------------------|---|
| \$ | <i>Rs</i> 2,844.66 | ✓ |
| \$ | <i>Rs</i> 241.60   | X |
| \$ | <i>Rs</i> 169.90   | X |
| \$ | <i>Rs</i> 450.60   | X |
| \$ | <i>Rs</i> 758.10   | X |
| \$ | <i>Rs</i> 42.10    | ✓ |
| \$ | <i>Rs</i> 133.40   | X |
| \$ | <i>Rs</i> 561.70   | X |
| \$ | <i>Rs</i> 1,933.20 | X |

**TOTAL \$ 2,494.90****10% \$ 249.49****\$ 2,245.41****Special Nett**

- 1 REAR BUMPER CLIP
- 1SET FENDER SCREW
- 1 TYRE
- 1 RIM
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

|    |                  |     |
|----|------------------|-----|
| \$ | <i>Rs</i> 65.00  | } X |
| \$ | <i>Rs</i> 60.00  |     |
| \$ | <i>Rs</i> 300.00 |     |
| \$ | <i>Rs</i> 350.00 |     |
| \$ | <i>Rs</i> 150.00 |     |
| \$ | <i>Rs</i> 200.00 |     |
| \$ | <i>Rs</i> 130.00 |     |

**TOTAL \$ 125.00****TOTAL PARTS \$ 2,370.41****LABOUR**

Towing fees

\$ *Rs* 170.00 X

**Trans-cab Auto Services Pte Ltd****AAD2103-017**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD604S**

To transfer of door fittings, attachment and perform water seepage test.

\$ 300.00 601

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.

\$ 380.00 601

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 1,400.00 4001

To rust-proofing and apply undercoat of the affected areas.

\$ 240.00 301

Putty and spray painting of the affected portion.

\$ 1,400.00 4401

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 201

**TOTAL \$ 4,750.00****Over All Total \$ 7,120.41****LUMP SUM (REPAIR DAY)****20 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: