

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5357Y**AAD2103-***Not Authored
Resuming B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

05 MAR 2021**SHD5357Y**

JTDKB3FU703078756

TOYOTA

PRIUS

26/02/2021

CHINA

11/01/2019

PART**LIST**

1	COVER, REAR BUMPER	\$	CR1	442.60	✓
1	COVER, REAR BUMPER, LOWER	\$	in	15.40	X
1	FILLER, REAR BUMPER EXTENSION, RH	\$	m/cr1	123.70	✓
1	GUARD, REAR BUMPER, CENTER	\$	B7	576.30	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	n	332.70	X
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	B7	1,294.90	✓
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	n	97.40	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	in	193.50	X
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	n	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	n	98.90	X
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	n	21.90	✓
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	n	34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	n	15.40	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	in	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	in	206.70	X
1	WEATHERSTRIP, REAR DOOR, RH	\$	in	180.10	X
1	PANEL SUB-ASSY, QUARTER, RH	\$	B7	871.50	✓
1	DUCT ASSY, QUARTER VENT, RH	\$	n11	67.00	✓
1	REINFORCEMENT, QUARTER WHEEL HOUSE, INNER RH	\$		58.50	?
1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$		296.20	?
1	PANEL SUB-ASSY, QUARTER WHEEL HOUSE, INNER RH	\$		544.00	?
1	LINER, REAR WHEEL HOUSE, RH	\$	n17	139.80	✓
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	in	594.80	X
1	ABSORBER ASSY, SHOCK, REAR RH	\$		127.00	?
1	COVER, REAR SUSPENSION ARM, RH	\$		49.70	?
1	ARM ASSY, UPPER CONTROL, REAR RH	\$		420.80	?
1	ARM ASSY, REAR SUSPENSION, NO.1 RH	\$		239.20	?
1	ARM ASSY, REAR SUSPENSION, NO.2 RH	\$		497.50	?

Trans-cab Auto Services Pte Ltd**AAD2103-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5357Y

1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30	7
1	PANEL SUB-ASSY, BACK DOOR	\$	1,147.80	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	925.60	X
1	STAY ASSY, BACK DOOR, LH	\$	242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	61.00	X
1	PANEL ASSY, DECK TRIM SIDE, RH	\$	355.90	✓
1	BOX, DECK FLOOR, RH	\$	313.60	X
1	BOARD, REAR FLOOR, NO.1	\$	519.00	X
1	LENS AND BODY, REAR LAMP, RH	\$	502.00	✓
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	451.80	7
TOTAL		\$	14,178.70	
25%		\$	3,544.68	
		\$	10,634.03	

Special Nett

1	REVERSE SENSOR	\$	700.00	X
1	FENDER LINER CLIP	\$	75.00	✓
1	FENDER CLIP	\$	75.00	X
1	REAR BUMPER CLIP	\$	65.00	501N
1	END PANEL INNER TRIM CLIP	\$	60.00	X
1	CLIP(FOR REAR DOOR TRIM BOARD)	\$	65.00	X
1	BOOT STICKER TRANSCAB	\$	100.00	X
1	BOOT STICKER 65553333	\$	100.00	X
1	REAR DOOR STICKER "6555-3333"	\$	100.00	601N
1	TYRE	\$	350.00	801N
1	RIM	\$	1,879.40	✓
2	WINDSCREEN SEALANT	\$	150.00	X
1	WINDSCREEN MOULDING	\$	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
TOTAL		\$	4,049.40	
TOTAL PARTS		\$	14,683.43	

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2103-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5357Y

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	<i>nn X</i>
Towing Fees	\$	150.00	<i>501</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	<i>601</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>901</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>1001</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	<i>901</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>601</i>
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	170.00	<i>Repair X</i>
TOTAL	\$	5,240.00	
Over All Total	\$	19,923.43	

(PART-BY-PART) Repair Days

*20 Days**7 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: