

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT3878D
Accident Date : 26-Feb-2021

No. : 06355

Date : 05-Mar-2021

Our Ref : 021037 (AIG) / CHAN

PAGE : 1

CANFORD ELECTRICAL PTE LTD
421 TAGORE INDUSTRIAL AVENUE
#02-25 TAGORE 8
Singapore 787805

ESTIMATED COST OF REPAIR FOR OPEL COMBO L2H1 1.6 CDTI GBF6326R
=====

1 pc LH side mirror assy	790.00	

	790.00	
Less 10% :	79.00	

		711.00
To spray lh side mirror cover		80.00
To remove lh side door inner trim board for remove & renew side mirror		100.00

Total :	S\$	891.00
		=====

Singapore Dollars Eight Hundred and Ninety One
Only