

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06355

Vehicle Insured : SKT3878D
Accident Date : 26-Feb-2021

Date : 05-Mar-2021

Our Ref : 021037 (AIG) / CHAN

PAGE : 1

CANFORD ELECTRICAL PTE LTD
421 TAGORE INDUSTRIAL AVENUE
#02-25 TAGORE 8
Singapore 787805

Not Notified

Return Bepaint

1 day

ESTIMATED COST OF REPAIR FOR OPEL COMBO L2H1 1.6 CDTI GBF6326R
=====

1 pc LH side mirror assy

CM 790.00 ✓

790.00

Less 10% : 79.00

711.00

To spray lh side mirror cover

80.00 *50/*

To remove lh side door inner trim
board for remove & renew side
mirror

100.00 *60/*

Total : S\$ 891.00
=====

Singapore Dollars Eight Hundred and Ninety One
Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: