

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0193/2021/HR
DATE : 5-Mar-21
WIP : 17947

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/2/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR VISHAL VIJAY
ADDRESS : 135 SUNSET WAY
#10-09
SINGAPORE 597158
TELEPHONE : HP +65 9816 2863
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800110662-02
VEHICLE NO : **SKM 1371 Z**
MODEL CODE : A5 SPORTBACK 2.0 TFS
MODEL YEAR : 24/9/2018
ENGINE NO : CVK 067613
CHASSIS NO : WAUZZZF57JA129768
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Mar-21
PLACE OF ACCIDENT : 10 ANSON RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 1371 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 280.00	x
2	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	350. ✓
3	TO DISMANTLE AND RENEW RHS REAR DOOR. TO REPAIR RHS REAR FENDER. TO REMOVE AND REINSTALL RHS SIL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,800.00	1000. ✓
4	TO RESPRAY RHS REAR DOOR, DOOR HANDLE, RHS FRONT DOOR, RHS REAR FENDER AND RHS SILL PANEL TRIM.	\$ 4,200.00	1200 Door handle : 100 550 x 2 = 1100 1200 ✓
5	TO RENEW RHS REAR RIM & TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	x
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,152.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 1371 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR DOOR - RH <i>Distorted</i>	1	\$ 3,884.00	<i>3107-20</i>	
2	REAR DOOR OUTER DOOR SEAL - RH <i>new</i>	1	\$ 222.00	<i>172.60</i>	
3	BONDING AGENT <i>NE new</i>	1	\$ 49.00	<i>? X</i>	
4	CLEANING SOLUTION <i>NE new</i>	1	\$ 68.00	<i>? X</i>	
5	APPLICATOR <i>NE new</i>	1	\$ 8.00	<i>? X</i>	
6	REAR DOOR ATTACHMENT PARTS - RH <i>new</i>	1	\$ 129.00	<i>+ X</i>	
7	REAR DOOR CATCH - RH <i>NE new</i>	1	\$ 120.00	<i>? X</i>	
8	REAR DOOR HANDLE TRIM PLATE - RH <i>new</i>	1	\$ 88.00	<i>+ X</i>	
9	REAR DOOR HANDLE INTERIOR TRIM - RH <i>NE new</i>	1	\$ 136.00	<i>? X</i>	
10	REAR DOOR HANDLE HOUSING - RH <i>NE new</i>	1	\$ 8.00	<i>? X</i>	
11	REAR DOOR HANDLE MOUNTING BAR - RH <i>NE new</i>	1	\$ 164.00	<i>? X</i>	
12	REAR DOOR WINDOW REGULATOR - RH <i>new</i>	1	\$ 368.00	<i>? X</i>	
13	REAR DOOR WINDOW REGULATOR W/ MOTOR - RH <i>new</i>	1	\$ 313.00	<i>? X</i>	
14	REAR DOOR WINDOW ATTACHMENT PARTS <i>new</i>	1	\$ 130.00	<i>? X</i>	
15	REAR DOOR WINDOW ADHESIVE TAPES <i>new</i>	1	\$ 212.00	<i>? X</i>	
16	REAR DOOR TRIM PLATE - RH <i>new</i>	1	\$ 164.00	<i>+ X</i>	
17	REAR ALUMINIUM RIM - RH <i>new</i>	1	\$ 1,690.00	<i>+ X</i>	
18	STONE CHIP <i>new</i>	S/N	\$ 180.00	<i>+ X</i>	
19	SUNDRIES <i>new</i>		\$ 192.00	<i>? X</i>	
TOTAL SPARE PARTS			\$ 8,125.00		
TOTAL LABOUR CHARGES			\$ 8,152.00		
GRAND TOTAL			\$ 16,277.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *05/03/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: