



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Ms Leong Choy Kit 43 Hindhede Walk #05-09 Singapore 587973 Mobile: 96796980		
			Document No. 0				
			Document Date 25/03/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXRKT E1	24/07/2019	SMN0596U	0	60522	69DS/SMN0596U
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B23F3201182583		2NR5376618	60	Raymond Seah L M	22/03/2021	8.00	25/03/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP VEH:YH 33S ACC DATE:05/03/2021 TP INS:CHINATAIPING NO OF REPAIR DAYS:05 DATE-IN:22/03/2021 DATE SURVEY:22/03/2021 BY:LKK-RASUL -TP/DS CLAIM				30.00	
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP59			180.00	
3	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR FRONT BONNET				60.00	
4	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	*			720.00	
5	B	BP-RES2 TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.	*			1180.00	
6	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	0619			183.16	
7	1	S52161-0K040 PIECE,RR BUMPER	2.00	4.10		8.20	
8	2	S53301-0D280 HOOD SUB-ASSY22	1.00	924.70		924.70	
For & on behalf of		Customer's Signature	Charge Summary			Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle _____				3,286.06	
			Parts 932.90			GST 7.00% 230.02	
			Labour 2,170.00			Less 0.00	
			Sublet 183.16				
			Lubrication/Fluid 0.00				
		Others 0.00			Amount Due 3,516.08		

Company Copy