



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR EF2211D

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT  
64 CECIL STREET  
#04/#05 IOB BUILDING  
SINGAPORE 049711  
63476100

Vehicle & Document Information

WIP No 48761  
Reg No/Reg Date EF2211D / 03/05/2016  
Date In/Mileage / 0  
Chassis No WDD2050402R160118  
Engine No 27491030584371  
Make/Model MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX  
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	05/03/2021/ 15:41	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :21004625203 // 04-03-2021 DRIVE IN:05-03-2021 // TP CAR NO:SLT4965S (INDIA INTERNATIONAL INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
S BPNSUB SUPPLY & TRANSFER 1PC REAR LEFT RIM PURCHASE ORDER NO:				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE,REPAIR & INSTALL SUPPORT ASSY FROM VEHICLE FRAME.				1920.00
A BPIRES RESPRAY REAR LEFT DOOR, REAR LEFT FENDER, REAR BUMPER & LEFT WING MIRROR HOUSING				1950
M LH/R DISC WHEEL <i>SCA</i>	1.00	582.12	00.00	582.12
M LEFT WING MIRROR SIGNAL LAMP <i>repair</i>	1.00	189.12	00.00	189.12

THIS IS NOT AN OFFICIAL TAX INVOICE  
ESTIMATE  
RASM  
Hp 9000068  
6 days  
11/03/21 @ 1610  
Resy after repair 1440  
1950

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 6,071.24  
7% GST on 6071.24 424.99  
Total Payable 6,496.23

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg