LIU'S BROTHER AUTO ENGINEERING WORKSHOP Invoice/Ref No: GBE5662G210224 No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883 ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com Estimate Customer Name: AIG Asia Pacific Insurance Pte Ltd Date: Address Motor Claims Department Vehicle No: 78 Shenton Way #07-16 Model/Make: Toyota Hiace AIG Building Singapore 079120 Van Turbo 5DR Manual Item **Original Descriptions Of Parts** No. Quotation / Estimation Rear **Tailgate** Bod (4.2) \$ 1,956.20 2 Tailgate "70 KM/H" Sticker nu 15.00 Tailgate "8 PAX" Sticker 3 nec 15.00 Tailgate Windscreen Glass Moulding WS 4 219.00 Tailgate Windscreen Glass Sealant 5 50.00 6 Bumper 599.50 7 Bumper Clips 1 set 65.00 Bumper Reverse Sensor Shahl 8 \$ 220.00 **End Panel Outer** 9 \$ 566.10 10 **End Panel Sealant** 50.00 11 "Corporate" Advertisement & Art Work 500.00 Remove and refix rear tailgate components & wiper mechanism 100.00 Remove and refix rear bumper reverse sensor

Total Parts & Labour of estimate for damaged vehicle

Remove & reinstall Tailgate Glass to facilitate repairs

\$ 5,735.80

Total amount in Lump Sum Basis for repaired vehicle

Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs

To putty & spray painting & including touch up paint on accident affectecd a

To apply Rust Proofing, reseal tuff-coating treatment on accident area

SDLS:



80.00

600.00

500.00

80.00

120.00

M/s Liu's Bro Auto Engrg Wks

not Author whe Afferyer while while

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-3068-50

06-03-21

Revised

Quotation /

Cost Of Repair

SIN

SIN

GBE5662G

SN 10

SN 10

SN

SN

SN

450 5/2

Ay