

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
TAN SUI LIN		Cust No/Name	/TAN SUI LIN
BLK 18A HOLLAND DRIVE		Reg No/Reg Date	SMJ9395U / 26/03/2019
#18-463		Date In/Mileage	/ 0
SINGAPORE 272018		Chassis No	VF72RHNZWJ4371182
Contact No Mobile: 97561372		Engine No	10XK132277926
		Make/Model	CIT/C3 AIRCROSS FEEL 1.2 PURETECH 110 S&
		Colour/Trim	Z4P PASSION RED / 4YF AMBIANCE SERIE

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	08/03/2021/ 12:45		442 / CocoLu	16270

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR REAR FENDER LH, REAR END PANEL TAILGATE				2000.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER TOP PANEL, TAILGATE, REAR FENDER LH REAR END PANEL				1140.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				100.00
M SUNDRY C&C LOGO				40.00
M SUNDRY Sundry				20.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				225.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
M REAR BUMPER	1.00	942.00	0.00	942.00
M OVERRIDER LH	1.00	615.00	0.00	615.00
M BUMPER MOULDING	1.00	482.00	0.00	482.00
M BUMPER BRACKET	1.00	249.00	0.00	249.00
M BUMPER BRACKET	1.00	155.00	0.00	155.00
M BRACKET SET LATERAUX D/G	1.00	432.00	0.00	432.00
M BUMPER BRACKET	1.00	418.00	0.00	418.00
M BADGE ASS	1.00	73.00	0.00	73.00
M BADGE	1.00	58.00	0.00	58.00
M BADGE	1.00	58.00	0.00	58.00
M WING PROTECTOR LH	1.00	188.00	0.00	188.00

Confirm & accepted by

Parts	3,670.00
Labour	3,635.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	60.00
Total (w/o GST)	7,365.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.