

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HUO HUI JUN
BLK 455A ANG MO KIO STREET 44
#30-09
SINGAPORE 561455

Estimate No: MC1901798
Date: 05 Mar 2021
Policy No: GA438404
Veh Reg No: SMJ987X
Make/Model: VOLKSWAGEN GOLF R
2.0L 5DR 5K1RX7

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 04/03/2021
TP Veh Reg No: GBH7171C

Estimate Repair Cost to Vehicle No :SMJ987X

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	2,293.15	
2 REAR BUMPER LOWER GARNISH LH	1 PC	999.35	
3 REAR BUMPER LOWER GARNISH REFLECTOR LH	1 PC	66.90	
4 REAR BUMPER SIDE RETAINER LH & RH	2 PC	93.50	
5 REAR BUMPER CENTRE RETAINER	1 PC	112.45	
6 REAR BUMPER CLIPS	12 PC	30.00	
7 REAR BUMPER REINFORCEMENT	1 PC	606.05	
8 REVERSE SENSOR LH INNER & OUTER	2 PC	389.50	
9 REVERSE SENSOR HOLDER	4 PC	129.00	
		4,719.90	
	Less 10%	471.99	4,247.91
Special Nett			
10 REAR VIEW CAMERA -CHECK PRICE	1 PC	0.0000	
11 REAR BUMPER LOWER GARNISH COVER LH -CHECK PRICE	1 PC	0.0000	
12 NUMBER PLATE	1 PC	35.00	
		35.00	35.00
LABOUR			
13 TO REMOVE AND REINSTALL/REPLACE REAR VIEW CAMERA	1 PC	60.00	
14 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00	
15 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
16 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR END PANEL, REAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	
17 TO SPRAY REAR BUMPER, END PANEL	1 PC	400.00	
		980.00	980.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : HUO HUI JUN
BLK 455A ANG MO KIO STREET 44
#30-09
SINGAPORE 561455

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 04/03/2021
TP Veh Reg No: GBH7171C

Estimate No: MC1901798
Date: 05 Mar 2021
Policy No: GA438404
Veh Reg No: SMJ987X
Make/Model: VOLKSWAGEN GOLF R
2.0L 5DR 5K1RX7

Estimate Repair Cost to Vehicle No :SMJ987X

Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 5,262.91
Add GST @ 7%			368.40
Total Amount Payable			S\$ 5,631.31

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED THIRTY ONE AND CENTS THIRTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE