

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : PA7882E

Accident Date : 8/3/2021

Location : CTE TOWARDS CITY BEFO BRADDELL ROAD EXIT LANE 4

TPALG

Ceilia

Model: '0YOTA HIACE COMMUTER
(8/9/2008)

3P: SMM9584A (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Red</i>	492.57	✓	-
2	10pcs	Rear bumper clips <i>Red</i>	-	30.00	✓
3	2pcs	Rear bumper screw clips <i>Red</i>	-	20.00	✓
4	2pcs	Rear bumper o/s & n/s retainer <i>Red</i>	362.70	55	-
5	1 pc	Rear tail gate <i>Painted</i>	2,810.86	2150	-
6	1 pc	Rear tail gate chrome moulding <i>Red</i>	486.2	x	-
7	1 pc	Rear tail gate 'TOYOTA' emblem <i>Red</i>	67.60	-	-
8	1 pc	Rear tail gate '70kmph' emblem <i>Red</i>	-	15.00	✓
9	1 pc	Rear windscreen sealant <i>Red</i>	-	100.00	60
10	1 pc	Rear windscreen moulding <i>Red</i>	-	240.00	16
11	1 pc	Rear tail gate weatherstrip <i>Red</i> NN	420.00	x	-
12	1 pc	Rear end panel <i>Repairs</i>	495.17	x	-
13	1 pc	Rear end panel inner trim <i>Red</i>	292.60	x	-
14	8pcs	Rear end panel inner trim clips <i>Red</i> NN	-	32.00	✓
15	1 pc	Rear lock upper <i>Red</i>	543.60	289	-
16	2pcs	Rear reverse sensor <i>Red</i>	-	280.00	200 (2N)
Sub-Total:			5,971.30	717.00	0.00
3054.17 S.N: 470			25%	0%	0%
2290.62			After Less %:	4,478.48	717.00
2290.62					
Labour			800.00 600		
1		To dismantle damaged parts, straighten & welding.	600.00	✓	-
2		To spray painting.	180.00	120	-
3		To remove and refit rear windscreen	100.00	30	-
4		To check wiring.	80.00	✓	-
5		To re-seal anti-rust. <i>1430</i>	Sub-Total:	1,760.00	-
Total:			6,955.48	-	-
After Less 20%:			5,564.38	-	-

Chan San Choon

Director

DipEng, AAE MIM(MS)E(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

- No legal modification is allowed
- Supplementary item(s) must be surveyed and accident call
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

PA7882E ESTIMATEPg1

Adrian Lj total 4190.62
N/S 09/03/21. L/S: 3.3k.

04 Days

Mobil 1



PAYNOW