

Mr Hsiang Tony

119 P Adhead  
L/S to 7700 /  
5 days.

FASTECH AUTO PTE LTD  
1 KAKI BUKIT AVE 6  
01-48 S'PORE 417883

VEHICLE No: XD 6069H

NETT

2PCS TAILLAMPS @\$650.00 495 (102) N/scr 1,300.00 1pc

S.NETT ITEM

1PC	TAILGATE	Beaf 3000 (50% S/N)	\$6,800.00	50% 1500
1SET	TAILGATE 'CORPORATE' STICKER	neu	\$800.00	400
4PCS	TAILGATE HINGES @\$180.00	Beaf	\$720.00	2pc 360
1PC	TAILGATE '60 KM/h STICKER	neu	\$20.00	10
1PC	TAILGATE LOWER MEMBER	R	\$3,000.00	X
1PC	REAR SAFETY BAR BUMPER & BRACKET	Beaf	\$2,500.00	1500
1SET	REAR SAFETY BAR BUMPER REFLECTIVE STRIP	in	\$80.00	X
1PC	REAR CENTRE CROSS MEMBER	Body	\$2,100.00	1500
1PC	REAR CENTRE CROSS MEMBER LOWER TRAY PANEL	Body	\$2,500.00	1800

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$180.00	50
LABOUR FOR REPAIR & STRAIGHTEN REAR CHASSIS	\$800.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,500.00	1200
TO PUTTY & SPRAY PAINTING	\$1,800.00	900
<b>TOTAL</b>	<b>\$25,150.00</b>	

P-495  
102  
-----  
P-445.50  
S/N-7070  
L-270  
-----  
9,681.5  
202  
-----  
7748

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: