

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

200 / Adnan

TAN CHEE HWEE
 BLK 188C RIVERVALE DRIVE #04-1050
 SINGAPORE 543188

ESTIMATE

Repair Code : CLM15202

Date in : 06/03/2021

Vehicle Num. : SJJ2633P

Model : HONDA STREAM 1.8L A

Chassis/Eng# : JHMRN68408S205234/R18A12805234

Contact : 96870871

TP China.
 Denise.

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	773.00	<i>688</i> 773.00
REAR BUMPER LOWER BRACKET L/R <i>Best</i>	2	8.60	<i>✓</i> 17.20
REAR BUMPER SCREW COVER L/R <i>new</i>	2	16.50	<i>X</i> 33.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	18.70	<i>✓</i> 37.40
REAR BUMPER TOW HOOK COVER <i>Deformed</i>	1	11.70	<i>✓</i> 11.70
REAR END PANEL <i>Dented</i>	1	353.10	<i>✓</i> 353.10
REAR END PANEL 'LOWER' <i>Dented</i>	1	105.00	<i>✓</i> 105.00
REAR END PANEL INNER TOP GARNISH <i>Deformed</i>	1	165.00	<i>✓</i> 165.00
REAR END PANEL INNER TOP GARNISH CLIPS <i>new</i>	6	6.50	<i>10</i> 39.00
REAR END PANEL LOCK STRIKER <i>Best</i>	1	27.20	<i>✓</i> 27.20
REAR END PANEL LOWER L/R <i>Repaired</i>	2	40.30	<i>X</i> 80.60
REAR EXHAUST ALUMINIUM HEAT SHIELD <i>new</i>	1	43.80	<i>X</i> 43.80
REAR EXHAUST CHROME TAIL PIPE <i>Best</i>	1	116.70	<i>✓</i> 116.70
REAR EXHAUST GASKET <i>new</i>	1	36.50	<i>✓</i> 36.50
REAR EXHAUST RUBBER MOUNTING <i>new</i>	3	12.50	<i>X</i> 37.50
REAR EXHAUST SILENCER BOX <i>Dented</i>	1	514.20	<i>✓</i> 514.20
REAR FENDER INNER TRIM GARNISH L/R <i>cracked</i>	2	226.55	<i>✓</i> 453.10
REAR FLOOR INNER TOP BOARD COVER L/R <i>cracked</i>	2	145.00	<i>✓</i> 290.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TAN CHEE HWEE

BLK 188C RIVERVALE DRIVE #04-1050

SINGAPORE 543188

Contact : 96870871

ESTIMATE

Repair Code : CLM15202

Date in : 06/03/2021

Vehicle Num. : SJJ2633P

Model : HONDA STREAM 1.8L A

Chassis/Eng# : JHMRN68408S205234/R18A12805234

REAR FLOOR PANEL	<i>Buckled</i>	1	1060.50	✓	1,060.50
REAR TAILGATE	<i>Distorted</i>	1	903.00	✓	903.00
REAR TAILGATE 'LOGO' EMBLEM	<i>3 New</i>	1	21.00	✓	21.00
REAR TAILGATE 'STREAM' EMBLEM	<i>1 New</i>	1	36.50	✓	36.50
REAR TAILGATE DAMPER L/R	<i>2 Dmg</i>	2	112.10	✓	224.20
REAR TAILGATE HINGES L/R	<i>2 New</i>	2	44.40	X	88.80
REAR TAILGATE INNER HANDLE GARNISH	<i>1 New</i>	1	25.00	X	25.00
REAR TAILGATE INNER TRIM BOARD	<i>1 New</i>	1	158.50	✓	158.50
REAR TAILGATE MECHANISM LOCK	<i>1 Damaged</i>	1	119.40	✓	119.40
REAR TAILGATE NUMBER PLATE LAMP L/R	<i>2 New</i>	2	38.00	X	76.00
REAR TAILGATE OUTER GARNISH	<i>1 Missing</i>	1	151.90	✓	151.90
REAR TAILGATE OUTER GARNISH CLIPS	<i>4 New</i>	4	6.50	✓	26.00
REAR TAILGATE OUTER LOCK HANDLE	<i>1 New</i>	1	63.80	X	63.80
REAR TAILGATE RUBBER GUIDE STOPPER L/R	<i>2 New</i>	2	8.00	✓	16.00
REAR TAILGATE WEATHER STRIP	<i>1 New</i>	1	116.90	✓	116.90
REAR TAILGATE WINDSCREEN GLASS	<i>1 Shattered</i>	1	1235	✓	1235
REAR TAILGATE WINDSCREEN INNER GARNISH 'TOP'	<i>1 New</i>	1	28.40	X	28.40
REAR TAILGATE WINDSCREEN INNER GARNISH L/R	<i>2 New</i>	2	35.00	X	70.00

*** This is a computer-generated document which requires no signature.***

page 2

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN CHEE HWEE
 BLK 188C RIVERVALE DRIVE #04-1050
 SINGAPORE 543188

Contact : 96870871

ESTIMATE

Repair Code : CLM15202

Date in : 06/03/2021

Vehicle Num. : SJJ2633P

Model : HONDA STREAM 1.8L A

Chassis/Eng# : JHMRN68408S205234/R18A12805234

REAR TAILGATE WINDSCREEN MOULDING	<i>new</i>	1	65.00	✓	65.00
REAR TAILGATE WIPER ARM	<i>3 Damsd</i>	1	38.90	✓	38.90
REAR TAILGATE WIPER ARM COVER		1	9.00	✓	9.00
REAR TAILGATE WIPER ARM RUBBER SEAL	<i>re</i>	1	10.00	✓	10.00
REAR TAILGATE WIPER MOTOR	<i>Damsd</i>	1	245.50	✓	245.50
REAR TAILGATE WIRE HARNESS	<i>Not new</i>	1	181.00	X	181.00
REAR TAILLAMP L/R	<i>cracked</i>	2	352.50	✓	705.00
REAR TAILLAMP PANEL L/R	<i>RH Dented</i>	2	145.90	<i>145.80</i>	291.80
REAR TAILLAMP SCREW COVER L/R	<i>Not new</i>	4	5.60	X	22.40
REAR TOOL SPONGE TRAY	<i>Dented</i>	1	126.50	✓	126.50
REAR TYRE JACK	<i>new</i>	1	215.00	X	215.00
REAR TYRE JACK COVER	<i>Dented</i>	1	50.00	✓	50.00
SPARE TYRE BRACKET	<i>Best</i>	1	116.90	✓	116.90
SPARE TYRE SCREW LOCK - SET	<i>Not new</i>	1	23.20	X	23.20
Subtotal before discount					9,353.10
Percentage discount 20%					1,870.62
Sub-total 1					7,482.48
REAR 3RD ROW PASSENGER SEAT LEATHER LINING	<i>Not new</i>	2	450.00	X	900.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN CHEE HWEE
 BLK 188C RIVERVALE DRIVE #04-1050
 SINGAPORE 543188

Contact : 96870871

ESTIMATE

Repair Code : CLM15202

Date in : 06/03/2021

Vehicle Num. : SJJ2633P

Model : HONDA STREAM 1.8L A

Chassis/Eng# : JHMRN68408S205234/R18A12805234

REAR BUMPER CLIPS - SET <i>new</i>	1	30.00	<i>✓</i>	30.00
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	400.00	<i>200</i>	400.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	50.00	<i>60</i>	100.00
REAR FLOOR PANEL INSULATOR SOUND MAT <i>new</i>	1	400.00	<i>250</i>	400.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	<i>✓</i>	30.00
REAR TAILGATE NUMBER PLATE <i>Best</i>	1	25.00	<i>✓</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>Deformed</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE REVERSE CAMERA <i>aged</i>	1	800.00	<i>380</i>	800.00
REAR TAILGATE WINDSCREEN GLASS INNER SEAL <i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET <i>new</i>	1	30.00	<i>X</i>	30.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	<i>✓</i>	60.00
Subtotal before discount				2,875.00
Percentage discount 0%				0.00
Sub-total 2				2,875.00
Parts-total				10,357.48

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	<i>✓</i>	60.00
To remove, reinstall tailgate windscreen	<i>120</i>	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>140</i>	140.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN CHEE HWEE
 BLK 188C RIVERVALE DRIVE #04-1050
 SINGAPORE 543188

Contact : 96870871

ESTIMATE

Repair Code : CLM15202

Date in : 06/03/2021

Vehicle Num. : SJJ2633P

Model : HONDA STREAM 1.8L A

Chassis/Eng# : JHMRN68408S205234/R18A12805234

To send vehicle for cleaning, shampoo, upholstery and cushion seat.

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

80 180.00
 1200 1,500.00
 80 150.00
 1500 1,800.00
 100 120.00
 ✓ 80.00

3360

Labour Total

4,180.00

Parts & Labour Total

14,537.48

*** This is a computer-generated document which requires no signature.***

page 5

total: 91167.56

L/S: 8.9K.

09 Days.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8.9K.