



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0196/2021/HR
DATE : 14-Feb-21
WIP : 18595

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR NG BOCK ANN
ADDRESS : 46 LAKESIDE DRIVE
#02-12
SINGAPORE 648324
TELEPHONE : HP +65 9733 5761
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00666170
VEHICLE NO : **SJX 9955 R**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 30/8/2019
ENGINE NO : CHZ C29924
CHASSIS NO : WAUZZZ8V7KA080957
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Feb-21
PLACE OF ACCIDENT : TAMPINES AVE 4 SINGAPORE



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJX 9955 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00
3	TO RESPRAY REAR BUMPER.	\$	900.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00
TOTAL LABOUR CHARGES		: \$	<u>2,422.00</u>

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJX 9955 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PAI
			S/NETT
1	REAR BUMPER	1	\$ 1,944.00
2	REAR BUMPER FIXING PARTS	1	\$ 193.00
3	REAR BUMPER GUIDE SECTION LH / RH	1	\$ 32.00
4	REAR BUMPER LOWER SPOILER	1	\$ 237.00
5	REAR LIGHT REFLECTOR - LH / RH	1	\$ 82.00
6	REAR BUMPER IMPACT BAR	1	\$ 603.00
7	REAR BUMPER IMPACT BAR BRACKET LH / RH	2	\$ 54.00
8	REAR PARKING SENSOR INNER / OUTER	2	\$ 488.00
9	REAR PARKING SENSOR SEAL RING	4	\$ 14.00
10	SUNDRIES		\$ 200.00
TOTAL SPARE PARTS		:	\$ 3,847.00
TOTAL LABOUR CHARGES		:	\$ 2,422.00
GRAND TOTAL		:	\$ 6,269.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



RTS & PRICES

REMARKS



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT