



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

Estimation

Date: 8/3/2021
Vehicle: SJZ2111U
Make / Model: MERCEDES E200
Chassis:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER X R	1	\$ 2,159.00	\$ 2,159.00 X
2	REAR BUMPER SIDE BRACKET RH X Svc	1	\$ 128.00	\$ 128.00 X
3	REAR BUMPER LOWER SIDE BRACKET RH X Svc	1	\$ 110.00	\$ 110.00 X
4	REAR FENDER RH X R	1	\$ 2,544.00	\$ 2,544.00 X
5	REAR FENDER COWLING RH X Svc	1	\$ 321.00	\$ 321.00 X
6	REAR DOOR RH / CH	1	\$ 2,587.00	\$ 2,587.00 2,165
7	REAR DOOR OUTER MOULDING RH / Nec	1	\$ 198.00	\$ 198.00 X
8	SIDE SKIRTING RH / CH	1	\$ 1,025.00	\$ 1,025.00 855
9	SIDE SKIRTING CHROME MOULDING RH X Svc	1	\$ 154.00	\$ 154.00 X
10	REAR WHEEL RIM RH / CK	1	\$ 1,865.00	\$ 1,865.00 1,250
11	REAR SHOCK ABSORBER RH X Svc	1	\$ 698.00	\$ 698.00
12	REAR WHEEL BEARING / Jam	1	\$ 304.00	\$ 304.00 250
13	REAR WHEEL HUB RH / BT	1	\$ 384.00	\$ 384.00 238
14	REAR LOWER ARM RH / BT	1	\$ 587.00	\$ 587.00 450
15	REAR UPPER ARM RH X Svc	1	\$ 512.00	\$ 512.00 X
16	REAR KNUCKLE ARM RH / BT	1	\$ 754.00	\$ 754.00 650
				\$ 14,330.00 6,056
			Less 10%	\$ 1,433.00 -10%
			Total	\$ 12,897.00 5,450.4
S/Nett items:				
1	FRONT BUMPER CLIPS SET / Nec	1	\$ 50.00	\$ 50.00 30
2	FRONT FENDER SEALANT X Svc	1	\$ 100.00	\$ 100.00 X
3	FRONT FENDER COWLING CLIPS SET X Svc	1	\$ 50.00	\$ 50.00 X
4	FRONT TYRE RH X Svc	1	\$ 350.00	\$ 350.00 X
				\$ 550.00 30
Labour to:				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00 700
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00 400
3	TO CHECK ELECTRICAL WIRING	1	\$ 120.00	\$ 120.00 30
4	TO REMOVE AND REFIT FRONT BUMPER SENSOR	1	\$ 150.00	\$ 150.00 X
5	TO REMOVE AND REFIT FRONT UNDERCARRIAGE (Rear)	1	\$ 450.00	\$ 450.00 150
6	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00 60
7	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 250.00	\$ 250.00 50
8	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00 40
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00 40
	Repair day - 4 days			\$ 3,240.00 1,470
	45 / After paint photo			
Sun Pin (1/1)			Parts Replacement Amount	\$ 13,447.00

09/03/2021

	Total Amount for Labour	\$ 3,240.00
	Total Amount	\$ 16,687.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

$$\begin{array}{r}
 5,450.4 \\
 30 \\
 1,470 \\
 \hline
 6,950.40 \\
 - 20\% \\
 \hline
 5,560.32
 \end{array}$$

215
\$5,500.00

4 days.