

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref :

DATE 10/3/2021

M/S AIG

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLH8033T

TO SUPPLY :

List Items

01)	1 PC	REAR BUMPER	22/02	581.20	\$ 629.80	=
02)	10 PCS 15/	REAR BUMPER CLIPS	22/02		\$ 60.00	=
03)	1 PC	REAR BUMPER REINFORCEMENT	22/02		\$ 420.10	X
04)	1 PC	REAR BUMPER REFLECTOR	22/02		\$ 54.80	X
05)	1 PC	REAR BUMPER RH RETAINER	22/02		\$ 55.30	X
06)	1 PC	BOOTLID "CAMRY" EMBLEM	22/02		\$ 49.90	X
07)	1 PC	BOOTLID LOGO	22/02		\$ 66.80	X
08)	1 PC	BOOTLID "2.4" EMBLEM	22/02		\$ 39.60	X
					\$ 1,376.30	
					LESS 25% \$ (344.08)	
					\$ 1,032.23	
09)	1 Set Rear	REVERSE SENSOR		Should	\$ 395.50	200 s/w
10)		REMOVE AND REAR SENSOR			\$ 100.00	-50
11)		TUFF COAT		11	\$ 100.00	X
12)		TO REMOVE,RENEW PARTS,REPAIR BOOTLID & END PANEL			\$ 680.00	300
13)		WIRING CHECK (REAR)			\$ 30.00	20
14)		SPRAY PAINTING (REAR)-3 PORTION			\$ 780.00	500
					<u>\$ 3,117.73</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: