

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 15 Mar 2021

Preliminary Advice

Insured Vehicle No	: SLK2554E		
TP Vehicle No	: SJQ2983S	Accident Date	: 07/03/2021
Make	: HONDA VEZEL	Assignment Date	: 08/03/2021
Date of Inspection	: 09/03/2021	Est. Duration of Repair	: 18
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,174.76
Revised Amount	:S\$	12,421.16
Check Items (Estimated)	:S\$	3,891.68
Total	:S\$	16,312.84

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- (X) Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.