ASS. REC. BY:	121003078/Kt
ennerh	ASSIGNMENT
From:	
Estimated Cost: Date:	Veh No: \(\int \int \int \int \int \int \int \int
OD VIP INS I TP RES I OD RES I EVA / INV I MY	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
To inspect Vehicle No:	Truck / Traller or (A)
at Wedness and	Make: /tonda Veze/ c.c 1896
of Chen 13	toe Colour M.P. White AC: Insured / Std / NI / NA
Insured:	Sp.Reading /1653/ T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	C/No: RU1 . 1203002
Sum Insured: Excess:	Gen. Cond: Good Fair / Poor / Burnt
(Client's Record)	Steering: Inor@/ Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
The state of the s	Modi: Nii / S/Rim / STDA/Rim or
(Policy Condition)	Tyre Size: F: 215155R17
Remark: The veh had commenced its N/S	O/S RS/DIIN/EXNOVA (OV.55)
repair at the time of inspection.	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
Bal. or Market Value: \$ 65/c	
IDAC Accident Rport: Consistent?: Yes or No	Front Rear
GIA / PR Seen: Consistent?: Yes or No	mm rysar. 7 mm
Est Repairs: A days Res.: Yes or No	7/2/2 mm
Lum Sum: /- B./ % 3 Val.: Yes or No	7/3/20
	Survey held at
CA / REV / REP. / 24 HRS Vehicle: IN	Des. of Damages: Frt / Reas 1 O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
	A CONTRACTOR OF THE CONTRACTOR
PART BY PART \$12,458.68, 18	BDAYS
RED: 4716.08;27%	
Section 20	
Car Francisco & Francis Africa Age	
The company of the co	Page 18
a/Time, File Pass to? : Prell. Report	Davis 04 Davis 40
. Frem. Report	Days Of Repair: 18
; Final Report	Resurvey No. of Trip: Survey Fee:
	Transportation:
Add	Fee: Site Insp (\$) _s.Rssi
	: Interview (\$), F.F.
port Format :	Later days (C

Cheng Hoe Motor Pte Ltd

SJQ 2983 S TP/MS1G

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

MSIG INSURANCE (S) PTE LTD (SGX) M/S: ES2190206/YISHUN **Estimate No:** 16 RAFFLES QUAY 09 Mar 2021 #24-01 HONG LEONG BUILDING Date: 5091018768-03 Policy No: SINGAPORE 048581 **SJQ2983S** Veh Reg No: FAX: 62257402 TEL: 68277660 Not Suthains
Resurry B4 paint
18day, HONDA HONDA VEZEL Make/Model: ATTN: Motor Claim Department **1.5X CVT** Chassis No: RU11205002 TP/MSIG WS Ref: L15B4405002 Engine No: Claim Type: Third Party 23/05/2017 Reg. Date: 07/03/2021 Accident Date:

TP Veh Reg No:

SLK2554E

	Estimate Repair Cost	to Vehicle No :SJQ2983S				PAGE:1/2	
	Description	U	/Price	Quantity	List Price	Amount	
					<u>S\$</u>	<u>S\$</u>	
	List Price				Bi		
1	REAR BUMPER	1.0	532.10	1 PC	532.10		
2	REAR BUMPER LH REFLECTORS	0157	148.50	2 PCS	297.00	4	
3	REAR BUMPER CLIPS	7	3.90	6 PCS	Me 23.40	一	
4	REAR BUMPER LH SIDE PAD		195.00	1 PC	Ju 195.00		
5	REAR WINDSCREEN GLASS MOULDING		118.50	1 PC	Ma 118.50	-	
6	REAR TAILGATE		997.00	1 PC	Ry 997.00	-	
7	TAILGATE EMBLEM (VEZEL)		45.30	1 PC	na 45.30	-	
8	TAILGATE INNER LOCK		96.20	1 PC	In 96.20		
9	TAILGATE INNER RUBBER		101.70	1 PC	Cer 101.70	2	
10	TAILGATE INNER BOARD		153.40	1 PC	Bux 153.40	7-	
11	The state of the s		225.70	1 PC	225.70	7	
12	TAIL CATE DEEL ECTODS	015 ?	276.50	2 PCS	553.00	4	
	TAILLAMPS ALS GA	0/57	482.40	2 PCS	964.80	4	
14	REAR FENDER WHEEL ARC GARNISHS		150.30	2 PCS	Bu 300.60		
	REAR END PANEL		411.90	1 PC	R 411.90	_	
16	REAR END PANEL INNER TOP GARNISH		98.00	1 PC	98.00	1	
	REAR END PANEL CLIPS		3.90	3 PCS	Mer 11.70	1_	
	REAR SPARE TYRE PANEL		787.50	1 PC	R4 787.50	_	
19	REAR SPARE TYRE PANEL TOP TOOL BOX		142.80	1 PC	CM 142.80	2	
20	REAR SPARE TYRE PANEL TOP BOARD		135.00	1 PC	Bu 135.00		
21	REAR SPARE TYRE PANEL UNDER COVER		190.10	1 PC	190.10	_	
22	REAR SPARE TYRE PANEL UNDER COVER CLIPS		3.80	6 PCS	na 22.80		
	REAR SMART KEY SENSOR		80.50	1 PC	80.50		
	REAR EXHAUST PIPE		528.10	1 PC	528.10		
	REAR EXHAUST PIPE BUSHES		15.70	2 PCS			
26	REAR EXHAUST TOP HEAT SEAL	100	49.10	1 PC	49.10		
	CENTRE EXHAUST PIPE		680.10	1 PC	R 680.10	_	
	FRONT BUMPER		549.80	1 PC	Bu 549.80		
	FRONT BUMPER LH SIDE RETAINER		15.70	1 PC	DIT 15.70		
	FRONT BUMPER REINFORCEMENT		321.00	1 PC	321.00	i-	
	FRONT BUMPER REINFORCEMENT TOP GARNISHS		17.40		34.80	7	
	FRONT GRILLE TOP COVER		54.00		54.00	7	
	FRONT GRILLE LOGO		24.70		24.70	7	
	FRONT GRILLE CLIPS		3.80	4 PCS	15.20	7	
	FRONT BUMPER CLIPS		3.80		22.80		
	BONNET		892.50		R 892.50		
	HEADLAMPS		1,923.50	2 PCS		7	
38	HEADLAMP LOWER GARNISHS		37.50		CPA 75.00	2	
39	OUTSIDE TEMPERATURE SWITCH		49.50		49.50		
	X TO THE RESERVE OF THE PARTY O				13,674.70	- 15/A	
				Less 20%	2,734.94	10,939.76	

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.c Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

FAX: 62257402

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

ATTN: Motor Claim Department

TP/MSIG

Claim Type: Accident Date:

WS Ref:

Third Party 07/03/2021 **SLK2554E**

TP Veh Reg No:

Chassis No: Engine No: Reg. Date:

Estimate No:

Policy No:

Veh Reg No:

Make/Model:

Date:

1.5X CVT RU11205002

09 Mar 2021

SJQ2983S

5091018768-03

ES2190206/YISHUN

HONDA HONDA VEZEL

L15B4405002

23/05/2017

	Estimate Repair Cost to Vehi		PAGE:2/2		
	Description	U/Price	Quantity	List Price S\$	Amount S\$
	Special Net			Del	
40	REVERSE SENSOR	200.00	1 SET	200.00	
41	REAR WINDSCREEN GLASS GUM	40.00	1 PC	Mer 40.00	_
42	FRONT NUMBER PLATE	35.00	1 PC	Del 35.00	
				275.00	275.00
	Labour				
43	REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	
44	REMOVE & REFIX SEAT, CARPET, GARNISH, ETC	120.00	1 LA	120.00	- 1
45	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR	2,200.00	1 LA	2,200.00	20001
	TAILGATE, REAR WIPER, REAR LOCK ASSY, TO				
	STRAIGHTEN, KNOCK & REPAIR REAR BOTH				
	CHASSISS, CUT, WELD & RENEW REAR SPARE TYRE				
	COMPARTMENT, REAR END PANEL, KNOCK & REPAIR REAR				
	BOTH FENDERS & REALIGN THE STRUCTURE THE SAME				20.4
46	REMOVE & REFIX REAR UNDER CARRIAGE	250.00	1 LA	250.00	2201
47	REMOVE & REFIX REAR EXHAUST AND CHECK SYSTEM	120.00	1 LA		10d
48	PUTTY & RESPRAY ON TAILGATE, REAR BOTH	1,300.00	1 LA	1,300.00	12001
	FENDERS, BOTH TOP ROOF SIDE PANELS, REAR SPARE TYRE				
	COMPARTMENT, REAR PANEL & REAR AFFECTED AREAS				1
49	PANEL BEATING ON FRONT PORTION	600.00	1 LA	600.00	50d
50	PUTTY & RESPRAY ON BONNET, FRT SUPPORT PANEL, FRT	800.00	1 LA	800.00	7001
	BUMPER, REINFORCEMENT			A	100
51	TO MOUNT ON CAR-O-LINER, JACK & STRAIGHTEN	250.00	1 LA	Photo 250.00	
52	REMOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	60.00	1 LA	60.00	
53	REMOVE & REFIX EXHAUST AND CHECK SYSTEM	80.00	1 LA	80.00	
54	RUSTPROOFING	60.00		60.00	1
	The second secon			5,960.00	5,960.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary iten (s) must be result eved and is subject to final au provai from Insurance Company

Acknowledged by Repairer Signature:

Add GST @ 7% **Total Amount Payable** S\$ 18,376.99

Total

S\$ 17,174.76

1,202.23

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	853D
Vehicle Details	
Vehicle No.:	SJQ2983S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Mar 2021
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4405002
Chassis No.:	RU11205002
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,184.00
Original Registration Date:	23 May 2017
First Registration Date:	23 May 2017
Transfer Count:	0
Actual ARF Paid:	\$10,258.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2027
PARF Rebate Amount:	\$7,693.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$31,707.00
Total Rebate Amount:	\$39,400.00

The information contained herein is correct as at 08 Mar 2021

OK

G SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

08/03/2021 12:55 (SGT) Date of Submission 07/03/2021 10:25 (SGT) Date of Accident Exact Location of Accident Singapore CTE TOWARDS PIE(CHANGI) Additional Location Information Singapore Country/State of Loss

DETAILS OF OWN VEHICLE

SJQ2983S Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? CHOO KIM HUI, JONATHAN(ZHU JINHUI, JONATHAN) Name Of Registered Owner NRIC No SXXXX853D jchoo83@hotmail.com Email Address (Phone) +65-91916865 Mobile Phone No +65-91916865 Alternative Phone No

VEHICLE PARTICULARS

Honda Manufacturer Vezel Model Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Private car Vehicle Category

INSURANCE COMPANY

NTUC Name of Insurance Company Type of Coverage Comprehensive Fleet Policy 5091018768-03 Policy Number Cover Note Number 23/5/20-22/5/21

DRIVER

CHOO KIM HUI, JONATHAN(ZHU JINHUI,JONATHAN) Name of Driver SXXXX853D **NRIC No** 08/11/1983 **Date Of Birth** Indoor Occupation

Accident report SC1G21380004

Page 1 of 15

Date Of Driving Pass	11/12/2003	
Driving experience Gender	17 YEARS AND 3 MONTHS	
Mahila Musahas	Male	
	(Phone) +65-91916865	
Alt. Phone Number	+65-91916865	
	jchoo83@hotmail.com	
Address complement	105 WOODLANDS VIEW #08-09	
	-	
Postcode	737710	
Is the driver the policyholder?	Yes	
Does Driver Own Other Vehicles?	No	
Vehicle Registration Number of Other Vehicle Owned by Driver	140	
vehicle registration retailed of Street vehicle Street		
Insurance Company of Other Vehicle Owned by Driver	· · · · · · · · · · · · · · · · · · ·	
GENERAL INFORMATION OF THE ACCIDENT		And the property Alberta
		and the state of t
Type of Accident	Chain Collision	
Weather Conditions	Clear	
Road Surface	Dry	
process and a second of the se		
OTHER INFORMATION		
OTHER INFORMATION	The state of the s	and the state of t
		The state of the s
Was any foreign vehicle involved in the accident?	No	No. of the second
Number of vehicles involved in the accident	3	
Was anybody injured in the Accident?	No	
Was any injured conveyed to hospital by ambulance? Was any other material or property damaged?	-	
Number of Passengers (Including Driver)	Yes	
Has the driver been approached by unknown person(s)	2	
soliciting/offering accident claims assistance?	No	
PASSENGER 1		
PASSENGER I		
Name	PASSENGER	
Gender	Female	
Published the second of the se		
DETAILS OF POLICE ACTION	production of the second section of the second	Commence of the State of the said
Was the accident reported to the police?	No	
Was notice of intended Prosecution given?	No	
If yes, against whom?	-	
EVI.		
CIRCUMSTANCES OF ACCIDENT	agricus de la como esta de la compansión d	B. D. Barrelli Hallaning James
Service and the service of the servi		
REFER TO ATTACH.		An Arrange
ATTACHMENT(S)		erani e e e e e e e e e e e e e e e e e e e
The state of the s	the softening the soft of the	and the second second
Are accident photos available for attachment?	A CONTRACTOR OF THE CONTRACTOR	
Was there any video captured by Car Camera?	Yes	
Was there any audio recorded?	No	
,	No	
	75 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	at the man being
DETAILS OF OTHER	VEHICLE PROPERTY 1	
Vehicle Penistration Number		the state of the state of the state of
Vehicle Registration Number	SLK2554E	
Vehicle Manufacturer	-	
Vehicle ModelVehicle Variant	* Typescale Steeler	
Vehicle Colour Vehicle Category		
Name of Driver	Private car	
NRIC No	PAUL YEAP	
2 to construct the second of t	SXXXX480A	
of .		
Accident report SC1G21380004		Page 2 of 15

	Sticken	(change) PIC				
Sketch Plan		<- < <u> </u>		918 hp. 9	29835 25546 300480A 17253318 12253318 10009 1000 K	à
DDA - 732	MSTANCES OF THE	ACCIDENT 10:25aM	1 1 1 1 1 1 1 1 1 1	l he	9688533	0
Annt a Lifett and co Liami	an impact Ilide onto a notived in o I have I po evs alighted	on the VI front car.	and to stop Yav and w I got aidust of to that time	out and the services	moments inrge from realized us including	d
under y	note that your insu our own comprehe oregoing particulars an	nsive policy. Pl	lease check with	ne for you to sub	nore injormation.	age Claim
Policyholder's Signa Date & Time:	iture	Driver's Signature (If driver is not the Date & Time:	e policyholder) Claim Third Party	Name: NRIC/FII	ng Centre Personnel's Cfelda N Nd.:	