

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHUA SOON YAM
472 ANG MO KIO AVE 10
#06-870
SINGAPORE 560472

Estimate No: MC1901806
Date: 09 Mar 2021
Policy No: MT/00757307
Veh Reg No: SMC6001M
Make/Model: HYUNDAI ELANTRA
AD 1.6 GLS

ATTN:

Your Ref No: SMC6001M
Claim Type: Third Party → R15
Accident Date: 08/03/2021
TP Veh Reg No: SKB606L

L1212 2pm

Not Authorized
Recovery B4 paint

4 days

Estimate Repair Cost to Vehicle No :SMC6001M

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR FENDER RH	1 PC	1,892.00	X
2 REAR FENDER COWLING FRT RH	1 PC	60.40	X
3 REAR FENDER COWLING RR RH	1 PC	56.00	X
4 REAR FENDER COWLING CLIPS	8 PC	8.00	X
5 REAR FENDER MUDFLAP RH	1 PC	23.00	✓
6 REAR WINDSCREEN MOULDING	1 PC	74.20	X
7 REAR BUMPER	1 PC	459.40	✓
8 REAR BUMPER LOWER COVER	1 PC	250.10	X
9 REAR BUMPER REFLECTOR RH	1 PC	40.80	X
10 REAR BUMPER SIDE RETAINER RH	1 PC	44.30	✓
11 REAR BUMPER CLIPS	12 PC	24.00	✓
12 REAR BUMPER GUARD RH	1 PC	15.00	X
13 REAR WHEEL CAP RH	1 PC	44.60	X
14 REAR WHEEL BEARING W HUB RH	1 PC	454.00	?
15 SPORTS RIM RHR (R15)	1 PC	671.30	✓
		4,117.10	
	Less 20%	823.42	3,293.68
Special Nett			
16 TYRE RHR - CHECK PRICE	1 PC	0.00	X
17 INNER SEAL	1 PC	20.00	X
18 WINDSCREEN SEALANT	1 PC	40.00	X
		60.00	60.00
LABOUR			
19 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
20 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	X
21 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	801
22 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	60.00	X
23 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
24 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
25 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER LH. TO KNOCK & REPAIR REAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	5001
26 TO SPRAY REAR FENDER RH, REAR BUMPER.	1 PC	600.00	4001



HUA SOON YAM
2 ANG MO KIO AVE 10
6-870
SINGAPORE 560472

Estimate No: MC1901806
Date: 09 Mar 2021
Policy No: MT/00757307
Veh Reg No: SMC6001M
Make/Model: HYUNDAI ELANTRA
AD 1.6 GLS

o: SMC6001M
: Third Party
ate: 08/03/2021
g No: SKB606L

Estimate Repair Cost to Vehicle No :SMC6001M

ption	Quantity	List Price	Amount
		S\$	S\$
		1,860.00	1,860.00
Total			S\$ 5,213.68
Add GST @ 7%			364.96
Total Amount Payable			S\$ 5,578.64

SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED SEVENTY EIGHT AND CENTS SIXTY FOUR ONLY

Arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORIZED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: