

FBA 6566R

V43

Date:

handle bar	180	130	✓ BT
clutch lever	68	/	/ Cut
Balancer	40	30	/ Mis
MIRROR	55	/	/
crash bar	120	/	/ } Cut
gear pedal	88	68	/
Front Footrest LH	78	35	/ BT
Rear Footrest LH	78	25	/ Cut
Rear Footrest Bracket LH	180	145	/ BT
Rear shock LH	580	480	/ BT
Exhaust	1600	1600	/ D1
Front mudguard	240	140	/ CAA
gear sock	20	10	/ Cut
		2906	

Fuel Tank repaint 200 $\times$ NN $\times$ 10% = 2615.4
 tail cover repaint 100 ✓

Labour

400 200

2915.4

20% = 2300

2 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: