

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: S Three
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$77K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STW74Y Reg: 31 Jun 2014
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi Q5 2.0 cc 1984
 Colour: Silver A/C: Insured / Std / Nil / NA
 Sp. Reading: 104191 T. Radio: Insured / Std / Nil / NA
 Eng. No: _____
 C. No: WAUZZZ88R16A075437
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / STD A/Rim / STD A/Rim or
 Tyre Size: F: 235/55R19
 R: 235/55R19
 BS / DUN / EXNOVA / GY / FS / LIZA MIC / DHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I. 15-03-21
 Survey held at: W/S 1pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
col: 86614

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)
☐ : MSA (\$ _____)

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Notes

7/11/11

S THREE AUTOMOTIVE RECOVERY PTE LTD
 Blk 8 Sin Ming Industrial Estate
 #01-64/66 Singapore 575643
 Tel : 6284 1542 / 6284 1675
 Fax : 6487 5315
 sthreeautomotive@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Both parties are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO :
 ATTN : MOTOR CLAIM DEPT.

LP VEH NO

ESTIMATE REPORT 1st QUOTATION

JOB NO

OWNER'S PARTICULAR

CONTACT

NAME : THIERRY PAUL HENRI FORICHON

ADDRESS :

CHASSIS NO

LICENSE NO. SJW74Y TRAN:

ENGINE NO

MAKE / MODEL : AUDI Q5

OWNER'S INSURER :

ACCIDENT DATE : 4-Mar-20

JOB-CODE : TP S/A : JOEY

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC %	DISC-PRICE	SU R. DIS P	EV. PRICE
1	TAILGATE <i>X Repair</i>	1.00	4120.00	0.00	4120.00	Y	X
2	TAILGATE LOGO	1.00	85.00	0.00	85.00	Y	✓
3	TAILGATE EMBLEM <i>2.0T</i>	1.00	45.00	0.00	45.00	Y	✓
4	TAILGATE EMBLEM Q5	1.00	55.00	0.00	55.00	Y	✓
5	TAILGATE RUBBER BEADING <i>✓ CUT</i>	1.00	196.00	0.00	196.00	Y	✓
6	TAILGATE INNER TRIM BOARD <i>X</i>	1.00	254.00	0.00	254.00	Y	X
7	TAILGATE GLASS WITH MOULDING <i>X</i>	1.00	890.00	0.00	890.00	Y	X
8	TAILLAMP LH <i>X</i>	1.00	1390.00	0.00	1390.00	Y	X
9	TAILLAMP INNER COVER <i>X</i>	1.00	35.00	0.00	35.00	Y	X
10	REAR BUMPER <i>✓ CFA</i>	1.00	1580.00	0.00	1580.00	Y	1132.7
11	REAR BUMPER LOWER <i>✓ CE</i>	1.00	388.00	0.00	388.00	Y	✓
12	REAR BUMPER WIRING HARNESS FAN SENSOR <i>✓ DM</i>	1.00	632.00	0.00	632.00	Y	120(SN)
13	REAR BUMPER REFLECTOR LH <i>✓ CFA</i>	1.00	230.00	0.00	230.00	Y	178.2
14	REAR BUMPER REFLECTOR RH <i>X NN</i>	1.00	230.00	0.00	230.00	Y	X
15	REAR BUMPER INNER SPONGE <i>X NN</i>	1.00	150.00	0.00	150.00	Y	X
16	REAR BUMPER INNER PLASTIC <i>✓ BR</i>	1.00	175.00	0.00	175.00	Y	✓
17	REAR BUMPER BRACKET LH <i>✓ BT</i>	1.00	48.00	0.00	48.00	Y	✓
18	REAR BUMPER BRACKET RH <i>X NN</i>	1.00	48.00	0.00	48.00	Y	X
19	REAR BUMPER RETAINER LH <i>✓ BR</i>	1.00	75.00	0.00	75.00	Y	✓
20	REAR BUMPER RETAINER RH <i>X NN</i>	1.00	75.00	0.00	75.00	Y	X
21	REAR BUMPER TOWING COVER <i>✓ MS</i>	1.00	530.00	0.00	530.00	Y	45
22	REAR BUMPER LOWER COVER CENTRE <i>X NN</i>	1.00	330.00	0.00	330.00	Y	X
23	REAR BUMPER REINFORCEMENT <i>✓ BT</i>	1.00	980.00	0.00	980.00	Y	505.6
24	REAR END PANEL <i>✓ BUC</i>	1.00	520.00	0.00	520.00	Y	✓
25	REAR END PANEL INNER <i>X</i>	1.00	520.00	0.00	520.00	Y	X
26	REAR END PANEL INNER CROSSMEMBER <i>X</i>	1.00	720.00	0.00	720.00	Y	X
27	REAR END INNER CHROME PANEL <i>X</i>	1.00	180.00	0.00	180.00	Y	X
28	REAR END INNER GARNISH <i>X</i>	1.00	135.00	0.00	135.00	Y	X
29	EXHAUST PIPE CENTRE <i>✓ BT</i>	1.00	2450.00	0.00	2450.00	Y	977
30	EXHAUST PIPE MOUNTINGS <i>X NN</i>	1.00	160.00	0.00	160.00	Y	X
31	EXHAUST PIPE CHROME <i>✓ BT</i>	1.00	285.00	0.00	285.00	Y	80
32	EXHAUST MUFFLER <i>✓ BT</i>	1.00	2450.00	0.00	2450.00	Y	985

33	EXHAUST HEAT SHIELD	1.00	520.00	0.00	520.00	Y	X
34	KEYLESS SENSOR	1.00	580.00	0.00	580.00	Y	X
35	REAR FENDER LH	1.00	2580.00	0.00	2580.00	Y	350
36	REAR FENDER INNER SHIELD LH	1.00	225.00	0.00	225.00	Y	✓
37	REAR AIR VENT LH	1.00	60.00	0.00	60.00	Y	✓
38	REAR FENDER INNER SIDE PANEL LH	1.00	325.00	0.00	325.00	Y	X
39	REAR FENDER INNER SIDE TRIM LH	1.00	150.00	0.00	150.00	Y	X
40	REAR 1/4 GLASS WITH MOULDING	1.00	720.00	0.00	720.00	Y	X
TOTAL PARTS			25121.00		25121.00		

6125.5

-5%: 5819.22

SPECIAL NETT ITEM

1	TAILGATE TRIM BOARD CLIPS	1.00	50.00	0.00	50.00	Y	X
2	REVERSE SENSOR 4PCS	2.00	1120.00	0.00	1120.00	Y	300
3	REAR FENDER INNER TRIM CLIPS	1.00	50.00	0.00	50.00	Y	X
4	REAR FENDER INNER SHIELD CLIPS	1.00	50.00	0.00	50.00	Y	30
5	REAR BUMPER CLIPS	1.00	50.00	0.00	50.00	Y	30
6	REAR NO PLATE	1.00	50.00	0.00	50.00	Y	
7	REAR TAILGATE GLASS SEALANT	1.00	50.00	0.00	50.00	Y	
8	REAR TAILGATE GLASS INNER SEAL	1.00	50.00	0.00	50.00	Y	
9	REAR TAILGATE GLASS CLEANER & PRIMER	1.00	50.00	0.00	50.00	Y	
10	1/4 GLASS SEALANT	1.00	50.00	0.00	50.00	Y	
11	1/4 GLASS INNER SEAL	1.00	50.00	0.00	50.00	Y	
12	1/4 GLASS CLEANER & PRIMER	1.00	50.00	0.00	50.00	Y	
TOTAL (PARTS):			1670.00		1670.00		480

LABOUR

1	STRENGTHEN & PANEL BEAT ACCIDENT AREA	1.00	1400.00	0.00	1400.00	Y	600
2	SPRAY PAINTING ON AFFECTED AREA	1.00	1400.00	0.00	1400.00	Y	800
3	R&R TAILGATE COMPONENTS	1.00	180.00	0.00	180.00	Y	60
4	R&R AND RESET REVERSE SENSOR	1.00	150.00	0.00	150.00	Y	40
5	R&R EXHAUST PIPE SYSTEM	1.00	280.00	0.00	280.00	Y	60
6	R&R INNER TRIM & CARPET TO REPAIR	1.00	150.00	0.00	150.00	Y	60
7	RESPRAY KOTO TUFF ON ACCIDENT AREA	1.00	180.00	0.00	180.00	Y	7 60
8	CHECK WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	30
9	R&R REAR TAILGATE GLASS	1.00	150.00	0.00	150.00	Y	X
10	R&R REAR 1/4 GLASS	1.00	150.00	0.00	150.00	Y	X
11	R&R CARPET, SEATS & TRIM TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	X
TOTAL (LABOUR):			4240.00		4240.00		2010

TOTAL (LABOUR):

TOTAL PARTS & LABOUR

8309.22

-20%: 6650

EXCESS : S\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING ✓

PART-BY-PART OR LUMP-SUM ✓ : S\$

DATE OF SURVEY : 15/3/21

SURVEY BY :

CONTACT NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

FAX NO :