

ASS. REC. BY:

Steve

REP:

CS / SMD 21003103 / KE17f3

ASSIGNMENT

19/3/18

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

FBP 1449A

Policy No.

Claims No.

CMTD2100650/RUC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Sum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX 1584 G

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra

c.c

1591

Colour:

Beige

A/C:

Insured / Std / NI / N

Bp. Reading

44874

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

KMH0841CMJU-648523

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / B/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

27/2/21

D.O.I.

29/3/21

Survey held at

Mover

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear LH

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-62R

Finalize \$1884.40 (P/P. before GST). 3 repair days

red: 367.60; 16%

File/Time, File, Pass to?



: Prell. Report



: Final Report

File/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Invs

(\$



: Weekend

(\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

RECEIVED:

AMOUNT / P/P. \$ 1884.40