

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBB 8014Z
Vehicle Model : NISSAN URVAN
Accident Date : 01.03.2021
Original Reg Date : 27.02.2010 (26.02.2025)

Date : 08.03.2021
Chassis : JN1MG2E25Z0760203
TP Ins. **CHINA**

ESTIMATE

1	1 pc	Tailgate		2,101.40	N b/-
2	1 pc	Tailgate Outer Garnish		463.50	NX ny
3	1 pc	Tailgate Outer Garnish Clips		30.00	NX un
4	1 pc	Tailgate Badge		56.60	N ny
5	1 pc	Tailgate Sticker Urvan		73.20	N ny
6	1 pc	Tailgate Sticker 3.0 DTi		73.20	N ny
7	1 pc	Tailgate Inner Lock		321.20	N ? bt
8	1 pc	Tailgate Lock Catch		69.20	N ny
9	1 pc	Tailgate Auto Lock Actuator		175.00	N ? ny
10	1 pc	Tailgate Lock Mechanism		329.50	N ? bt
11	1 pc	Tailgate Weatherstrip - photo		189.60	N ? int
12	2 pcs	Tailgate Stopper (Male)	42.00	84.00	NX ny
13	2 pcs	Tailgate Stopper (Female)	49.00	98.00	NX ny
14	1 pc	Tailgate Inner Trim Board		182.80	N ny
15	1 set	Tailgate Inner Trim Board Clips		40.00	N ny 20
16	1 pc	Tailgate Inner Cover Plate		85.30	NX ny
17	2 pcs	Tailgate Hinges	68.20	136.40	NX ny
18	2 pcs	Tailgate Absorber	262.80	525.60	NX ny
19	1 pc	Tailgate Windscreen Inner Seal		50.00	N ny
20	1 pc	Rear Bumper		695.50	N ny
21	2 pcs	Rear Bumper Side Retainers	39.00	78.00	N ny
22	1 set	Rear Bumper Clips		50.00	N ny
23	1 pc	Rear Bumper Step Panel		226.30	N bt
24	2 pcs	Taillamps	241.50	483.00	N ny
25	1 pc	End Panel (Outer) - photo		487.20	N ny
26	1 pc	End Panel (Inner)		536.50	N ny
27	1 pc	End Panel Top Trim		126.50	N ny
				7,767.50	5418.50
				Less 10%	776.75
					6,990.75
					4876.65

C/F

6,990.75

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBB 8014Z

B/F

6,990.75

Special Nett

1	1 pc	Rear Windscreen Sealant		60.00	nel
2	1 pc	Tailgate Sticker 70km/h		15.00	nel
3	1 pc	Tailgate Airport Sticker		60.00	nel
4	1 set	Reverse Sensor		250.00	200mm
5	1 set	Body Panel Joint Sealant		120.00	400mm
6	1 pc	Rear Number Plate		50.00	del 30

8 Pax' sticker

nel

115

420

Labour charge

Panel Beating		1,000.00	700.
Spray painting		1,000.00	800.
Check Wiring		30.00	✓
Anti rust		90.00	32
Remove and install rear winscreen.		140.00	120-
Remove and install tailgate parts.		90.00	60.
Remove and install reverse sensor		90.00	50

9,985.75

Less 20%

1,997.15

Lump sum

7,988.60

1770.

Tougher 97495749
WP 10/3/21 E 1/4m
06 days
L/S Repair after repair
for the C / Khantun

7066.65

485650

06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: