

QUOTATION

NO. : 37885

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 08/03/2021

CLAIM NO. : 11693

POLICY NO. : PNMC2020-00002819

FROM : HASRIANAH

VEHICLE NO. : FBQ0930C

MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
2	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00
3	BOX REAR KAPPA K47 MANTA - (REPORTED BY MECHANIC)	REPLACE	1.00	\$300.00	300.00
4	BRACKET BOX REAR (GIVI) P/N: 55428 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	65.00
5	COVER SIDE CENTRE RH (WHITE) P/N: 58117 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
6	COWLING FRONT RH (WHITE) P/N: 59594 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
7	EMBLEM (ABS) P/N: 56578 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$11.00	22.00
8	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
9	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$73.00	73.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*37885 *

bizSAFE₃



	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	GASKET EXHAUST PIPE P/N: 58162 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	<i>ner</i> 13.00
	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	<i>8</i> 8.00	\$63.00	<i>350</i> 504.00
12	LAMP TAIL ASSY P/N: 60928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$240.00	<i>320</i> 240.00
13	MIRROR RH P/N: 58187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	<i>cn7</i> 38.00
14	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	<i>cn7</i> 49.00
15	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	<i>17.5</i> 54.00
16	PANEL 2 (MATTE BLACK) RH P/N: 63492 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	<i>scr</i> 24.00
17	PIPE EXHAUST ASSY P/N: 58083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$423.00	<i>77</i> 423.00
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	<i>1</i> 1.00	\$30.00	<i>sent</i> 30.00 <i>14 s/n</i>
19	PROTECTOR EXHAUST P/N: 58086 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	<i>cn7</i> 40.00
20	REFLECTOR ASSY REAR <i>centre</i> P/N: 63813 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	<i>cm</i> 16.00
21	REFLECTOR REAR P/N: 67563 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	<i>n/sms o/s cm 2</i> 10.00
22	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$2.00	<i>ner</i> 10.00

SUB TOTAL

\$2,075.00

GST @ 7 %

\$145.25

GRAND TOTAL (SGD)

\$2,220.25

50% deposit required before ordering of parts.

Validity: 30 days

*37885 *

p-1571
s/n-14
L-350
1732-90
bizSAFE₃


 CERT NO : 2002-1-0363
 ISO 9001 : 2015

DescriptionActionQtyUnit PriceAmount

On Behalf of

Acknowledge & Accepted By

HOCK HIN CO PTE LTD



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*37885 *

bizSAFE₃