

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

LKK - Advan
C7PC

04/03/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chinn.
Ashes.

Accident date: 03/03/2021

Estimated repair cost for vehicle no: GBJ4394K TOYOTA HIACE VAN TURBO 5DR MT 19'

CHASSIS: JTFHT02P500248885

S/n	Qty	Items / List	U/price	Amount	
1	1	Rear Boot Lid <i>Disltd</i>		\$1,712.45	✓
2	2	Rear Boot Lid Hinge <i>2 new</i>	\$171.70	\$343.40	+
3	2	Rear Boot Lid Shock Absorber	\$374.45	\$748.90	+
4	1	Rear Boot Lid Toyota Hiace Sticker <i>new</i>		\$57.60	✓
5	1	Rear Boot Lid Emblem Logo <i>new</i>		\$41.10	✓
6	1	Rear Boot Lid Centre Moulding <i>Rehld</i>		\$281.90	✓
7	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$67.80	\$135.60	+
8	1	Rear Boot Lid Inner Lock <i>Jammed</i>		\$374.25	✓
9	1	Rear Boot Lid Inner Power Lock <i>Panel</i>		\$276.20	✓
10	1	Rear Boot Lid Inner Trimboard <i>torn</i>		\$581.10	165.30
11	10	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$65.00	20.
12	1	Rear Boot Lid Inner Trimboard Handle <i>new</i>		\$186.45	+
13	1	Rear Boot Lid Weatherstrip <i>cut</i>		\$381.90	289
14	1	Rear Boot Lid Windscreen <i>at</i>		\$1,355.00	1015
15	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$105.00	✓
16	2	Rear Tail Lamp <i>crushed</i>	\$371.50	\$743.00	✓
17	2	Rear Tail Lamp Panel <i>Repair</i>	\$355.80	\$711.60	+
18	2	Rear Tail Lamp Lower Cover <i>Rehld</i>	\$182.10	\$364.20	158.
19	2	Rear Tail Lamp Lower Cover Retainer <i>new</i>	\$171.45	\$342.90	+
20	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	✓
21	2	Rear Fender <i>Repair R.H</i>	\$1,989.90	\$3,979.80	+
22	2	Rear Fender Air Duct <i>R.H. Rehld</i>	\$172.45	\$344.90	65
23	1	Rear Bumper <i>Disltd</i>		\$374.45	✓
24	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	30
25	2	Rear Bumper Side Retainer <i>new</i>	\$131.35	\$262.70	✓
26	1	Rear End Panel Outer <i>Disltd</i>		\$581.10	✓
27	1	Rear End Panel Inner <i>Dented</i>		\$591.25	✓
28	1	Rear Floor Panel <i>Repair</i>		\$1,850.00	+

29	1	Rear Floor Panel Top Moulding	Best		\$174.10	✓
30	8	Rear Floor Panel Top Moulding Clip	new	\$6.50	\$52.00	20.
31	1	Rear Floor Panel Carpet	new		\$750.00	x,
32	1	Rear Floor Panel Plywood	new		\$550.00	x
33	1	Rear Plywood Box	new		\$2,000.00	400(SN)
34	1	Rear Spare Tyre Bracket	Best		\$172.10	✓
35	1	Rear Exhaust	Best		\$1,712.85	725.
36	1	Rear Centre Exhaust	new		\$1,829.10	x
37	2	Rear Exhaust Mounting	new	\$65.00	\$130.00	x.

8270.50

Subtotal :- \$24,258.90

6202873 S.N:400

S/n	Qty	Items / Special Nett	U/price	Amount
1	1	Rear Boot Lid 70km/H Sticker	new	\$20.00
2	1	Rear Boot Lid 4Pax Sticker		\$20.00
3	1	Rear Boot Lid Number Plate	Best	\$50.00
4	1	Rear Boot Lid Reverse Camera	Damaged	\$680.00
5	1	Rear Bumper Reverse Sensor	Damaged	\$350.00

630

Subtotal :- \$1,120.00

Labour charges

To remove & refit plywood box	\$500.00	120
To remove & refit trimboard and cushion	\$800.00	60
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To check wiring	\$100.00	30
Tuff kote	\$150.00	80
Towing	\$150.00	x
Panel beating	\$2,500.00	1400

Spray painting

~~\$2,200.00~~ 1300.

3210

Subtotal :- \$6,670.00

Total:- \$32,048.90

Supplementary: 235.98

Total: 10678.85

L/S: 8.5K

10-Days.

8.5K.

10 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

04/03/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 03/03/2021

Supplementary repair cost for vehicle no: GBJ4394K TOYOTA HIACE VAN TURBO 5DR MT

CHASSIS: JTFHT02P500248885

S/n	Qty	Items / List	U/price	Amount
1	2	Rear End Panel Side Extension <i>Rlt Bent</i>	\$214.65	\$429.30 <i>214.65</i>
2	4	Rear End Panel Lower Bracket <i>Bent</i>	\$35.00	\$140.00 <i>100</i>
Subtotal :-				<u>\$569.30</u>

314.65

Supplementary: 235.88