

386
Y DA
TT



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AUTO & GENERAL INSURANCE (SINGAPORE)

190 CLEMENCEAU AVENUE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

TEL: 6221 2111

ATTN: Motor Claim Department

Estimate No: ES2100025

Date: 09 Mar 2021

Policy No:

Veh Reg No: SMK1574S

Make/Model: NISSAN SYLPHY 1.6
CVT

Chassis No: MNTBBAB17Z0034965

Engine No: HR16940669C

Reg. Date: 29/03/2019

Your Ref No: -

Claim Type: Third Party

Accident Date: 08/03/2021

TP Veh Reg No: SKX4536M

*Not Notified
1/2mp @ 4450k
Missing After Rain
7 days*

Estimate Repair Cost to Vehicle No :SMK1574S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00	X
2 REVERSE SENSOR	350.00	1 SET	350.00	X
			410.00	410.00
Spare Parts				
3 REAR ANTENA BUZZER SENSOR	195.00	1 PC	195.00	X
4 BOOT EMBLEM 'SYLPHY'	88.90	1 PC	88.90	X
5 BOOT EMBLEM 'LOGO'	88.90	1 PC	88.90	X
6 BOOT HINGE - LH	131.80	1 PC	131.80	X
7 BOOT HINGE - RH	131.80	1 PC	131.80	X
8 BOOT LID TRIMBOARD	325.10	1 PC	325.10	X
9 BOOT LID TRIMBOARD CLIP	50.00	1 SET	50.00	X
10 BOOT LOCK	251.40	1 PC	251.40	X
11 BOOT REFLECTOR LH	318.20	1 PC	318.20	X
12 BOOT REFLECTOR RH	318.20	1 PC	318.20	X
13 REAR BODY PANEL	503.30	1 PC	503.30	X
14 REAR BODY PANEL TOP GARNISH	200.76	1 PC	200.76	X
15 REAR BODY PANEL TOP GARNISH CLIP	24.00	1 PC	24.00	X
16 REAR BOOT LID	980.15	1 PC	980.15	X
17 REAR BOOT LID WEATHERSTRIP	265.90	1 PC	265.90	X
18 REAR BUMPER	955.10	1 PC	955.10	X
19 REAR BUMPER BRACKET - LH	131.80	1 PC	131.80	X
20 REAR BUMPER BRACKET - RH	131.80	1 PC	131.80	X
21 REAR BUMPER CLIPS	50.00	1 SET	50.00	X
22 REAR BUMPER REFLECTOR - LH	78.05	1 PC	78.05	X
23 REAR BUMPER REFLECTOR GARNISH	78.05	1 PC	78.05	X
24 REAR BUMPER SPONGE	382.00	1 PC	382.00	X
25 REAR BUMPER SIDE RETAINER - LH	102.50	1 PC	102.50	X
26 REAR BUMPER SIDE RETAINER - RH	102.50	1 PC	102.50	X
27 REAR CHASSIS MEMBER -LH	798.50	1 PC	798.50	X
28 REAR FENDER - LH	1,189.50	1 PC	1,189.50	X
29 REAR FENDER INNER TRIM - LH	369.50	1 PC	369.50	X
30 REAR TAIL LAMP CLIP - LH	33.80	1 PC	33.80	X
31 REAR TAIL LAMP CLIP - RH	33.80	1 PC	33.80	X
32 REAR TAIL LAMP PANEL - LH	197.90	1 PC	197.90	X
33 REAR WINDSCREEN MOULDING	189.10	1 PC	189.10	X
34 TAIL LAMP LH	428.25	1 PC	428.25	X

255

607

95750

325

126

365



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AUTO & GENERAL INSURANCE (SINGAPORE)
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
TEL: 6221 2111
ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 08/03/2021
TP Veh Reg No: SKX4536M

Estimate No: ES2100025
Date: 09 Mar 2021
Policy No:
Veh Reg No: SMK1574S
Make/Model: NISSAN SYLPHY 1.6
CVT
Chassis No: MNTBBAB17Z0034965
Engine No: HR16940669C
Reg. Date: 29/03/2019

Estimate Repair Cost to Vehicle No :SMK1574S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 TAIL LAMP RH	428.25	1 PC	428.25	X
36 REAR NUMBER PLATE LAMP - LH	85.15	1 PC	85.15	X
37 REAR NUMBER PLATE LAMP - RH	85.15	1 PC	85.15	X
			9,724.11	9,724.11
Labour				
38 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,200.00	1 JOB	2,200.00	1800
39 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,000.00	1 JOB	2,000.00	800
40 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	160.00	1 JOB	160.00	30
41 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	120
42 TO REMOVE/REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.	150.00	1 JOB	150.00	100
43 TO REMOVE/REFIT FUEL TANK TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	X
			4,910.00	4,910.00
			Total	SS 15,044.11
			Add GST @ 7%	1,053.09
			Total Amount Payable	SS 16,097.20

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND NINETY SEVEN AND CENTS TWENTY ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

report SS0221380006

180 Liang Kelvin
SXXX818F
26/01/1971
Outdoor