

ASS. REC. BY:

REF:

C12/210031201K

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140 P2588

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pro

c.c.

1788

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

135227

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB 3FU503 83096

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

NII / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

4/3/21

D.O.I.

8/3/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BL

15/7 61 km 8350a Car

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9258Z**AAD2103-**

Not Authored
Recovery After Paint
1/Lp @ 8350/h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 MAR 2021**SHD9258Z**

JTDKB3FU503083096

TOYOTA

PRIUS

04/03/2020

CHINA

30/08/2019

PART**LIST**

1	COVER, REAR BUMPER	\$	<i>B</i>	442.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>B</i>	332.70	✓
1	COVER, REAR BUMPER, LOWER	\$	<i>BU</i>	15.40	✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>B</i>	576.30	✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>B</i>	116.50	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>mgm</i>	117.70	✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$	<i>mgm</i>	123.70	✓
1	FILLER, REAR BUMPER EXTENSION, LH	\$	<i>B</i>	123.70	X
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>B</i>	1,147.80	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>CM</i>	925.60	✓
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>CM</i>	259.20	✓
1	WEATHERSTRIP, BACK DOOR	\$	<i>Dis</i>	372.30	✓
1	BOARD, BACK DOOR TRIM	\$	<i>Repost</i>	225.20	X
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	<i>B</i>	443.30	X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	<i>B</i>	451.80	✓
1	LENS AND BODY, REAR LAMP, LH	\$	<i>B</i>	502.00	X
1	LENS AND BODY, REAR LAMP, RH	\$	<i>B</i>	502.00	✓
1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>B</i>	355.90	X
1	BOX, DECK FLOOR, RH	\$	<i>B</i>	313.60	X
1	BOX, DECK FLOOR, LH	\$	<i>B</i>	313.00	X
1	BOARD, REAR FLOOR, NO.1	\$	<i>CM</i>	519.00	✓
1	BOX, DECK FLOOR, REAR	\$	<i>B</i>	105.80	X
1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>B</i>	355.90	X
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>B</i>	56.50	X
1	DUCT ASSY, QUARTER VENT, RH	\$	<i>B</i>	67.00	✓
1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>B</i>	871.50	✓
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>B</i>	139.80	X
1	SEAL, REAR BUMPER SIDE, RH	\$	<i>B</i>	88.50	X

Trans-cab Auto Services Pte Ltd**AAD2103-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9258Z

- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, REAR FLOOR (CTR)
- 1 COVER, DECK TRIM, REAR
- 1 PAN, REAR FLOOR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH
- 1 SWITCH ASSY, BACK DOOR OPENER
- 1 COVER, BACK DOOR LOCK
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH

\$	Sm	175.10	X
\$	Di	241.90	✓
\$	Bu	229.90	✓
\$	Sm	126.70	X
\$	R	583.40	X
\$	R	650.30	X
\$	Sm	467.00	X
\$	Sm	179.10	X
\$	Sm	30.20	X
\$	Sm	88.50	X
\$	R	871.50	X
\$	Sm	139.80	X
\$	Sm	242.50	X
\$	R	242.50	X
\$	R	61.00	X
\$	R	61.00	X

TOTAL	\$	14,254.70
25%	\$	3,563.68
	\$	10,691.03

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE TOYOTA LOGO
- 1 REAR TAILGATE WORDING 'PRIUS' } 25%
- 1 REAR TAILGATE WORDING 'HYBRID' }
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR FENDER LINER CLIP
- 1SET REAR BUMPER RETAINER CLIP
- 1 REAR NUMBER PLATE WITH HOLDER
- 1SET TAILLAMP LOWER CLIP

\$	Ncl	700.00	250sm
\$	Nu	95.00	50sm
\$	Nu	150.00	80sm
\$	Nu	200.00	✓
\$	Nu	130.00	30sm
\$	Nu	47.90	✓
\$	Nu	54.60	✓
\$	Nu	54.60	✓
\$	Nu	80.00	30sm
\$	Nu	80.00	30sm
\$	Nu	180.00	30sm
\$	Nu	250.00	X
\$	Nu	85.00	✓
\$	Nu	85.00	X
\$	Bt	140.00	45sm
\$	Nu	55.00	✓

Trans-cab Auto Services Pte Ltd**AAD2103-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9258Z

1SET TAILLAMP UPPER CLIP	\$	<i>nn</i>	55.00	<i>X</i>
1 END PANEL TRIM CLIP	\$	<i>nn</i>	65.00	<i>✓</i>
1 REAR SPOILER CLIP	\$	<i>nn</i>	70.00	<i>X</i>
TOTAL	\$		2,577.10	

TOTAL PARTS	\$	13,268.13
--------------------	-----------	------------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$		300.00	<i>1800</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	<i>1200</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	<i>18000</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	<i>X</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$		180.00	<i>600</i>
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>nn</i>	480.00	<i>X</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i>	480.00	<i>X</i>
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>nn</i>	380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$		380.00	<i>2500</i>
To check steering geometry and computer wheel alignment	\$		220.00	<i>600</i>

Trans-cab Auto Services Pte Ltd**AAD2103-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9258Z

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	906
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	13201
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 220.00	X
To replace, refix and top up coolant for radiator	\$	~ 170.00	X
To lift-up / out engine with gear box and refit.	\$	~ 440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	~ 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	~ 380.00	X
TOTAL	\$	10,290.00	
Over All Total	\$	34,249.15	

(PART-BY-PART) Repair Days**25 DAYS**

14 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: