

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SKK8873G [YOUR INSURED] & SDR983X [OUR CLIENT]
ON 08/03/2021.

ESTIMATED REPAIR COSTS FOR SDR983X

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET HH	\$ 2,980.10	X
1PC	BONNET INSULATOR HH	\$ 510.80	X
1PC	BONNET SEAL HH	\$ 150.90	X
1PC	BONNET LOCK HH	\$ 387.20	X
1PC	BONNET STRIKER LOCK HH	\$ 87.50	X
2PCS	BONNET HINGE LH / RH @ \$198.00 EACH HH	\$ 396.00	X
2PCS	HEAD LAMP LH / RH @ \$2,890.10 EACH HH o/s n/s mirror broken	\$ 5,780.20	X
2PCS	HEAD LAMP LOWER BRACKET LH / RH @ \$201.90 EACH HH	\$ 403.80	X
2PCS	HEAD LAMP ECU LH / RH @ \$1,689.80 EACH HH	\$ 3,379.60	X
1PC	HEAD LAMP WIRE HARNESS HH	\$ 1,992.00	X
1PC	FRONT GRILLE HH	\$ 682.00	X
1PC	FRONT GRILLE BASE CHROME	501.50	X
1PC	FRONT GRILLE CHROME CHROME	257.90	X
1PC	FRONT BUMPER CHROME	881.90	X
1PC	FRONT BUMPER GRILLE HH	\$ 482.00	X
2PCS	FRONT BUMPER FOG LAMP LH / RH @ \$510.01 EACH HH	\$ 1,020.02	X
2PCS	FRONT BUMPER FOG LAMP GARNISH LH / RH @ \$ 392.10 EACH HH	\$ 784.20	X
2PCS	FRONT BUMPER FOG LAMP HOLDER LH / RH @ \$278.40 EACH HH	\$ 556.80	X
1PC	FRONT BUMPER FOG LAMP WIRE HARNESS HH	\$ 1,930.00	X
1PC	FRONT BUMPER TOW HOOK COVER HH	\$ 78.20	X
1PC	FRONT BUMPER UNDER COVER HH	\$ 410.00	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$195.00 EACH HH	\$ 390.00	X
1PC	FRONT BUMPER SPONGE HH	185.20	X
1PC	FRONT REINFORCEMENT BAR HH	\$ 1,692.00	X
2PCS	FRONT REINFORCEMENT BAR BRACKET LH / RH @ \$391.20 EACH HH	\$ 782.40	X
1PC	FRONT SUPPORT PANEL HH	\$ 2,180.00	X
1PC	A/C CONDENSOR HH	\$ 2,009.80	X
1PC	A/C CONDENSOR SUCTION PIPE HH	\$ 982.40	X
1PC	A/C CONDENSOR DISCHARGE PIPE HH	\$ 1,004.20	X
1PC	RADIATOR ASSY HH	\$ 2,390.80	X

			\$ 692.38	X
1PC	RADIATOR FAN MOTOR HH		\$ 398.40	X
1PC	RADIATOR FAN BLADE HH		\$ 701.50	X
1PC	RADIATOR FAN COWLING HH		\$ 872.90	X
1PC	AIR FILTER HOUSING HH		\$ 2,880.58	X
2PCS	FRONT FENDER LH / RH @ \$1,440.29 EACH HH		\$ 461.80	X
2PCS	FRONT FENDER INNER SHIELD LH / RH @ \$230.90 EACH HH		\$ 1310.00	✓
1PC	BOOTLID <i>Dench</i>	1260.40	\$ 295.00	✓
1PC	BOOTLID LOGO HLC	90.00	\$ 2,450.00	✓
1PC	BOOTLID 'LEXUS' EMBLEM HLC	70.00	\$ 2,140.00	✓
1PC	BOOTLID 'IS250' EMBLEM HLC	80.00	\$ 697.80	✓
1PC	BOOTLID OUTER GARNISH WAVE	513.30	\$ 1,396.20	✓
2PCS	BOOTLID LAMP LH / RH @ \$698.10 EACH <i>H/S broken</i>	0/S HH	\$ 481.00	X
1PC	BOOTLID SWITCH HH	484.30	\$ 895.00	✓
1PC	BOOTLID LOCK <i>Dench</i>	423.40	\$ 590.00	✓
1PC	BOOTLID STRIKER LOCK <i>st</i>	205.00	\$ 610.00	✓
1PC	BOOTLID WEATHER STRIP <i>defunct</i>	293.10	\$ 711.00	✓
1PC	BOOTLID INNER TRIM <i>defunct</i>	561.80	\$ 601.00	X
2PCS	BOOTLID NO. PLATE LAMP LH / RH @ \$139.00 EACH HH		\$ 320.00	X
2PCS	BOOTLID HINGE LH / RH @ \$160.00 EACH SVL		\$ 2,194.20	✓
2PCS	TAIL LAMP LH / RH @ \$1,097.10 EACH <i>H/S broken</i>	0/S HH	\$ 996.40	✓
2PCS	TAIL LAMP PANEL LH / RH @ \$498.20 EACH <i>H/S Dench</i>	0/S HH	\$ 603.80	✓
2PCS	TAIL LAMP SIDE GARNISH TOP LH / RH @ \$301.90 EACH <i>H/S defunct</i>		\$ 622.40	✓
2PCS	TAIL LAMP SIDE GARNISH LOWER LH / RH @ \$314.20 EACH <i>H/S broken</i>		\$ 2,291.40	✓
1PC	REAR BUMPER <i>Dench</i>	854.00	\$ 296.00	✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$148.00 EACH <i>H/S st</i>	0/S HH	\$ 95.00	X
1PC	REAR BUMPER TOW HOOK COVER SVL		\$ 388.00	✓
2PCS	REAR BUMPER REFLECTOR LH / RH @ \$194.00 EACH <i>H/S broken</i>	0/S HH	\$ 384.00	✓
1PC	REAR BUMPER SPONGE <i>form</i>		\$ 491.20	X
1PC	REAR BUMPER UNDER COVER HH		\$ 356.10	X
1PC	REAR BUMPER CENTER BRACKET HH		\$ 1,692.20	✓
1PC	REAR REINFORCEMENT BAR <i>Dench</i>	580.00	\$ 394.00	X
1PC	REAR KEYLESS SENSOR HH		\$ 398.00	X
1PC	REAR KEYLESS BUZZER HH		\$ 1,892.40	✓
1PC	REAR END PANEL <i>Dench</i>	830.00	\$ 425.90	✓
1PC	REAR END PANEL TOP GARNISH <i>broken</i>	342.00	\$ 2,870.00	X
1PC	SPARE WHEEL PANEL HH		\$ 925.60	X
1PC	SPARE WHEEL PANEL TOP BOARD HH		\$ 1,380.00	X
2PCS	SPARE WHEEL QUARTER PANEL LH / RH @ \$690.00 EACH HH		\$ 405.90	X
1PC	SPARE WHEEL PANEL TOOL BOX HH	1445.00	\$ 5,960.00	✓
2PCS	REAR FENDER LH / RH @ \$2,980.00 EACH <i>H/S Dench</i>	0/S HH	\$ 2,028.20	✓
2PCS	REAR FENDER INNER TRIM LH / RH @ \$1,014.10 EACH <i>H/S defunct</i>		\$ 2,014.50	X
1PC	REAR EXHAUST PIPE HH	0/S HH	\$ 980.50	✓
1PC	REAR EXHAUST MUFFLER <i>st (Dench)</i>		\$ 210.00	X
1PC	REAR EXHAUST MOUNTING HH		\$ 2,298.00	X
1PC	REAR EXHAUST HEAT SHIELD HH		\$ 430.20	✓
1PC	REAR WINDSCREEN MOULDING HH HLC	122.50		✓

2 pcs Dam 2 pcs HN

4 Pcs	REAR BUMPER SENSOR	\$ 320.00 EACH	\$ 1280.00	✓	640.00
1 PC	REAR BUMPER SENSOR HARNESS WORKER		\$ 480.00	✓	

exclud.

16311.00
14679.90

PARTS SUM: \$ 87,687.38
PARTS LESS 10%: \$ 8,768.74
PARTS TOTAL: \$ 78,918.64

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY BONNET INSULATOR CLIPS HN	\$ 50.00	X
*	TO SUPPLY HEAD LAMP CLIPS HN	\$ 50.00	X
*	TO SUPPLY FRONT GRILLE CLIPS Hec	\$ 50.00	15/-
*	TO SUPPLY FRONT BUMPER CLIPS Hec	\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER GRILLE CLIPS HN	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER UNDER COVER CLIPS HN	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HN	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER LOWER LID CLIPS HN	\$ 50.00	X
*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS HN	\$ 50.00	X
*	TO SUPPLY REAR WINDSCREEN SEALANT Hec	\$ 80.00	40/-
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL HN	\$ 30.00	X
*	TO SUPPLY REAR WINDSCREEN INNER SEAL HN	\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT Hec	\$ 80.00	20/-
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS Hec	\$ 80.00	15/-
*	TO SUPPLY BOOTLID INNER TRIM CLIPS Hec	\$ 50.00	15/-
*	TO SUPPLY REAR BUMPER CLIPS Hec	\$ 50.00	20/-
*	TO SUPPLY REAR BUMPER LOWER LID CLIPS HN	\$ 50.00	X
*	TO SUPPLY REAR END PANEL SEALANT Hec	\$ 80.00	20/-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS Hec	\$ 50.00	15/-
*	TO SUPPLY REAR WHEEL HOUSING SEALANT HN	\$ 80.00	X
*	TO SUPPLY COOLANT HN	\$ 100.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 400.00	120/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	\$ 2,400.00	500/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	\$ 2,400.00	300/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	\$ 2,600.00	1200/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	\$ 2,600.00	900/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$ 200.00	HN
*	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	\$ 400.00	HN
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$ 500.00	120/-

- * TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS \$ 100.00 74
- * TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS \$ ~~150.00~~ 60/-
- * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS 3420.00 \$ ~~200.00~~ 30/-
- * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS \$ ~~300.00~~ 150/-

LABOUR & S/N TOTAL: \$ 13,810.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 92,728.64

09/03/2021 @ 1200hrs

Wet Antenna

4/5mm

10 days


Ryan

LKK Auto

Check Part prices

Check MV

Repair limit.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: