

F1

SMY3424E . 2016 Oct.

Mazda CX5 2188CC

TP Chinn

Denise

KE2FW122134.

Front Number Plate.	} cracked	30(SN) ✓
Front Number Plate Holder		30(SN) ✓
Front Bumper	Behind	1023.10. ✓
Front Bumper Side Holder x02	new	24.2 x 2 = 48.40 ✓
Front Bumper Clips.	new	30(SN) ✓
Front Bumper Reinforcement.	Dented	594.80. ✓
Front Bumper Sponge.	cracked	94.50 ✓
Front Bumper Undercover	} new	210.40. ✗
Front Bumper Undercover Clips.		30(SN) ✗
Front Bumper Fog Lamp x02	new	421.4 x 2 = 842.80 ✗
Front Bumper Fog Lamp Cover x02	new	72.4 x 2 = 142.80 ✗
Front Grille	cracked	550.80 ✓
Front Grille clips.	} new	20(SN) ✓
Front Grille Logo		4890. ✓
Front Grille Chrome Moulding.	cracked	198.70 ✓
Front Grille Inner Garnish.	Behind	195.40. ✓

SMY3424E.

Headlamp x 02	NH MR	3565.6 x 2 = 7131.20	X
Front Support Panel.	NH MR	621.80	X
Bonnet	Dented	1170	✓
Bonnet Lock.	NH MR	224.	X

Rear Bumper.	Distorted.	1281	✓
Rear Bumper Clips.	NH	30(SN)	✓
Rear Bumper Side Holder x 02	NH	30.8 x 2 = 61.60	✓
Rear Bumper Reflector x 02	RH ut	186 x 2 = 372	186
Rear Bumper Reinforcement.	Dented	543.40	✓
Rear Bumper Tow Cover x 02	RH dented	19.2 x 2 = 38.40	19.20
Rear Bumper Undercover RH.	torn	204.10.	✓
Rear Bumper Undercover Clips RH.	NH	30(SN)	✓
Rear End Panel	Dented	519.40	✓
Rear End Panel Top Garnish.	curled	134.90	✓
Rear End Panel Top Garnish Clips.	NH	20(SN)	✓
Rear End Panel Sealant.	NH	60(SN).	✓

SMV3424E.

Taillamp x 02	ut	520.4 x 2 = 1040.80 ✓
Tailgate	Dented	1448 ✓
Tailgate Lock	Dmg	250.80 ✓
Tailgate Weatherstripe	ut	285.60 ✓
Tailgate Inner Trim Board	crushed	750.40 ✓
Tailgate Inner Trim Board clips.	nu	30(SN) ✓
Tailgate Glass Moulding.	} nu	124.10 ✓
Tailgate Glass Sealant.		60(SN) ✓
Mazda Logo.	} nu	43.60 ✓
CX5 Wordimg.		54.50 ✓
Skyactiv Emblem.		72.60 ✓
Rees Fender Inner Trim Board x 02	RH	413.50
Rees Fender Inner Trim Board clips.	nu	413.5 x 2 = 827 60(SN) 30(SN)
Spare Tyre Panel Top Cover	nu	645.90 +
Rees Exhaust Pipe.	Bent	1551.10 ✓
Rees Exhaust Pipe Mounting.	nu	38.40 X
Rees Exhaust Heat Shield.	nu	269.90 +
Centre Exhaust Pipe.	Bent	1780. ✓

SMV 3424E.

Panel Beating (Front)

Spray Painting, (Front)

Wiring, (Front)

To remove condenser and to top up air con gas. 120 X

To remove radiator and to top up coolant. 120 X

Panel Beating (Rear)

Spray Painting (Rear).

Wiring (Rear)

To remove upholstery

To transfer tailgate fittings.

To remove tailgate g/s

To spray tuff coat

To remove rear and centre exhaust pipes.

~~1200~~ 500

~~800~~ 500

~~50~~ 30

~~1200~~ 800

~~1000~~ 800

~~50~~ 30

~~150~~ 80

~~150~~ 80

~~180~~ 120

~~150~~ 60

~~300~~ 160

List: 14689.20

Len: 11751.36

S.N: 390

Labour: 3160

Total: 15301.36

4/s: 12.2K.

11 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: