

ASS. REC. BY:

REP: SMO/21003127/K vd3Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Cam Del

of _____

Insured: _____

Policy No. _____

Claims No. CMTD2100698/SYHSum Insured: _____ Excess: WAIVE

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<u>N/S</u>	<u>O/S</u>

Bal. or Market Value: \$49k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Andrea Vehicle: IN / OUTVeh No: SLM 32392 Yr Regn: 07, 12Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer E200 c.c. 1796Colour: M. Grey A/C: Insured / Std / Nil / NASp. Reading: 180137 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WDD 2120482A 598779Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 243/40 ZR18R: 265/35 ZR18

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or Falken

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 0.5 mmL/Bal. 2 mm L/Bal. 0.5 mmD.O.A. 4/3/21 D.O.I. 10/3/2021

Survey held at _____

Des. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>10/3</u>	<u>Rear tyre not totally bald about 0.5mm.</u>
	<u>Wksp unable to locate 2nd parts.</u>
<u>27/4/21</u>	<u>Submit preli report-revised fig \$6354.15 check items \$2147.16</u>

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2) 27/4/21-TypistReport Format: OD

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

S + RS. \$ _____

Fees

Others

TOTAL

05/03/2021



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : ODIns Company : SOMPOExcess : Date of Accident : 04/03/2021Suggested Days of Repair : **Repair Estimate**Parts (a) Cost / List Price Items \$ -Plus/Less 10% \$ -Total of Cost / List \$ -(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ -Labour (Appendix B) \$ 2,050.00Total Repair Cost \$ 2,050.00

The above total will be subjected to 7% G.S.T.

Vehicle No. : SLM3239ZMake & Model : M/BENZ E 200Year of Manufacture : 2012Chassis No. : WDD2120482A598779Engine No. : Policy No. : Time of Accident : **In-house Vehicle Assessor**Case Owner : AndrewSignature :

Contact No

Front Counter Operation

Patrick Tia 6383 7466 PatrickTia@sparkcarcare.com

Brenda Ng 6383 7730 BrendaNg@sparkcarcare.com

Rohani 6383 7890 RohaniM@sparkcarcare.com

Workshop Operation

Ngo Toh Wee 6383 7656

Ngotw@sparkcarcare.com

William Wang 6383 8115

WilliamWangKS@sparkcarcare.com

Andrew Goh 6383 7362

Andrewcorneliusgoh@sparkcarcare.com

Not Authorized
Permy B4pain

Name of Surveyor : Kenneth
Company : CRK
Survey conducted on : 10/3/21 at

Remarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 05 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor : LeDate: 10/3/21

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLM3239Z Case Owner : Andrew

Make & Model : M/BENZ E 200 Year Manufacture : 2012

Chassis No : WDD2120482A598779 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front number plate with casing <i>CM</i>	1					✓
2	Front number plate bracket <i>SM</i>	1					X
3	Front bumper <i>CM</i>	1					✓
4	front bumper tow cover <i>mi'l</i>	1					✓
5	Front bumper carrier LH	1					?
6	Front bumper carrier RH	1					?
7	Front bumper clips <i>me</i>	10					✓
8	Front bumper rivets <i>me</i>	10					✓
9	Front bumper lower chrome LH <i>me</i>	1					✓
10	Front bumper lower chrome RH <i>me</i>	1					✓
11	Front bumper sensor outer LH <i>SM</i>	1					X
12	Front bumper sensor center LH <i>SM</i>	1					X
13	Front bumper sensor inn LH	1					?
14	Front bumper sensor outer RH <i>SM</i>	1					X
15	Front bumper sensor center RH	1					?
16	Front bumper sensor inn RH	1					?
17	Front bumper sensor spacer ring <i>me</i>	6					✓
18	Radiator grille <i>CM</i>	1					✓
19	Radiator grille emblem logo <i>me</i>	1					✓
20	Bonnet <i>R</i>	1					✓
21	Bonnet star logo <i>SM</i>	1					X
22	Bonnet spring element	2					?
23	Bonnet lock <i>Dis</i>	1					✓
24	Bonnet hinge LH <i>R</i>	1					X
25	Bonnet hinge RH <i>R</i>	1					X
26	Headlamp LH	1					?
27	Headlamp cover LH	1					?
28	Headlamp RH <i>CM</i>	1					✓
29	Headlamp cover RH	1					?
30	Headlamp lower bracket LH	1					?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

05/03/2021

1:06 PM

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLM3239Z Case Owner : Andrew

Make & Model : M/BENZ E 200 Year Manufacture : 2012

Chassis No : WDD2120482A598779 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Headlamp lower bracket RH	1					?
32	Front reinforcement <i>B₁</i>	1					✓
33	Brace panel <i>B₁</i>	1					✓
34	Front bumper center reinforcement	1					?
35	Front bumper sponge LH	1					?
36	Front bumper sponge RH	1					?
37	Front bumper sponge center <i>CM</i>	1					✓
38	Radiator air guide <i>CM</i>	1					✓
39	Radiator lower air guide	1					?
40	Radiator upper air guide	1					?
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

05/03/2021

Tel: 63837168 / 63837466 Fax:62844284,62815767

: 2012

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/03/2021 15:45 (SGT)
Date of Accident 04/03/2021 09:05 (SGT)
Exact Location of Accident 495A Tampines Ave 5, Singapore 529650
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLM3239Z

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner TEH SENG TOON
NRIC No SXXXX455H
Email Address movifund@gmail.com
Mobile Phone No (Phone) +65-98533789
Alternative Phone No (Office) +65-985334789

VEHICLE PARTICULARS

Manufacturer Mercedes
Model E200
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company Sompo
Type of Coverage Comprehensive
Fleet Policy No
Policy Number D20MTPV01008884
Cover Note Number -

DRIVER


Name of Driver TEH SENG TOON
NRIC No SXXXX455H

Describe Circumstances of the Accident

I was driving along Tampines Central 2. SLM32392. After exiting towards Tampines Ave 5 in the direction to PIE. There were a queue of vehicles just after the junction. The vehicle, SJZ 233P stopped suddenly. I stepped on the brake but was too late to avoid a collision.

Rear bumper of SJZ 233P was damaged. The front grille & bumper of SJZ 233P were damaged. A coolant or oil was leaking.

Time of Accident 9.05 am



Declaration

We declare the foregoing particulars are true in every respect.

COMFORTDELGRO ENGINEERING PTE. LTD.
383 SIN MING DRIVE
SINGAPORE 575711