

ComfortDelGro Engineering

205 Braddell Road S(579701)

(e) Signature of surveyor

ACCIDENT REPAIR ESTIMATE

our Ref:	
Type of Claim : OD	Vehicle No. : SLM3239Z
JF O CIMIN , OD	Make & Model : M/BENZ E 200
	Year of Manufacture : 2012
	Chassis No. : WDD2120482A598779
ns Company : SOMPO	Engine No.
Excess	Policy No. :
Date of Accident : 04/03/2021	Time of Accident :
Suggested Days of Repair :	In-house Vehicle Assessor
Repair Estimate	Case Owner : Andrew
Parts (a) Cost / List Price Items \$7299.7	7 Signature :
728.98	Contact No
Plus/Less 10% \$ -	Front Counter Operation
Total of Cost/List \$8029.75	Patrick Tia 6383 7466 Patrick Tia@sparkcarcare.com Brenda Ng 6383 7730 Brenda Ng@sparkcarcare.com
Total of Cost / List	Rohani 6383 7/30 Brendang@sparkcarcare.com
(b) Nett Price Items \$ -	
	Workshop Operation
Less \$	Ngo Toh Wee 6383 7656
T. J. CNI with	Ngotw@sparkcarcare.com
Total of Nett Item \$ -	William Wang 6393 9115
(c) Special Nett Items \$ 35.00	William Wang 6383 8115 WilliamWangKS@sparkcarcare.com
Fotal Parts Cost (Appendix A) \$ 306 4.75	Andrew Goh 6383 7362
	Andrewcorneliusgoh@sparkcarcare.com
Labour (Appendix B) \$ 2,050.00	Nos Wiha
Fotal Panair Cost 5 2.050.00	Not Nother Base
Fotal Repair Cost \$ 2,050.00	Mehrry Blepa.
The above total will be subjected to 7% G.S.T.	
	1/
Name of Surveyor	Menserh
Company	6146
Survey conducted on	10/3/21 at
Remarks By Surveyor	
(a) The repair of this vehicle is antiberized / is not auti	horized until further notice.
(b) Recommended Days of Repair :	05 day(s)
(c) Resurvey Required /	Not Required
(d) Excess \$	
(e) Signature of surveyor	Le Date: 10/3/21

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	: <u>SLM3239Z</u>	Case Owner	: Andrew
Make & Model	: <u>M/BENZ</u> E 200	Year Manufacture	: 2012
Chassis No	: WDD2120482A598779	Engine No	<u>0</u>
Sales Order	š	Supplier	*
Order By	#	Type of Claim	: <u>OD</u>

S/No	Part Description		оту	Cost	List	Nett		Disposition By
			¥	Price	Price	Price	S/N	Surveyor
1	Front number plate with casing	cm	1	4			\$35.00	~
2	Front number plate bracket	in		\$118-21				X
3	Front bumper	cm	1	\$908.39				
4	front bumper tow cover	Mil	1					-
5	Front bumper carrier LH		1					7
6	Front bumper carrier RH		1					7
7	Front bumper clips	M	10					<u> </u>
8	Front bumper rivets	M	10					<u></u>
9	Front bumepr lower chrome LH	M	1	\$55.69				ン 一 ス ス
10	Front bumper lower chrome RH	M	1	\$55.69				-
11	Front bumper sensor outer LH	Sin	1	\$174.36				X
12	Front bumper sensor center LH	Sm	1	\$174.36				X
13	Front bumper sensor inn LH		1	\$174.36				2
14	Front bumper sensor outer RH	S	1	\$174.36				X
15	Front bumper sensor center RH		1	\$174.36				7
16	Front bumper sensor inn RH		1	\$174.36				7
17	Front bumper sensor spacer ring	Ma	6	\$36.06				じ
18	Radiator grille	Cas	1	\$ 731.93				-
19	Radiator grille emblem logo	M	1					_
20	Bonnet	R	1	\$15-16.29				
21	Bonnet star logo	Sn	1	\$60.23				X
22	Bonnet spring element		2	\$40.68				7
23	Bonnet lock	ציום	1					<u></u>
24	Bonnet hinge LH	R	1	\$96.26				X
25	Bonnet hinge RH	n	1	\$96.26				X
26	Headlamp LH		1	\$683.25				7
27	Headlamp cover LH		1					1
28	Headlamp RH	CM	1	\$ 683.25				
29	Headlamp cover RH		1					7
30	Headlamp lower bracket LH		1	\$169.08				7

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No
: SLM3239Z
Case Owner
: Andrew

Make & Model
: M/BENZ E 200
Year Manufacture
: 2012

Chassis No
: WDD2120482A598779
Engine No
: 0

Sales Order
: 0
Supplier
: 0

Order By
: 0
Type of Claim
: OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Headlamp lower bracket RH	1	4169.08	11100	77.00	2,11	7
	Front reinforcement 34	1	\$349.25				<u></u>
33	Brace panel 4	1					-
	Front bumper center reinforcement	1	\$ 99.48				7
	Front bumper sponge LH	1	\$43.73				7
36	Front bumper sponge RH	1 -	\$43.73				7
37	Front bumper sponge center CM	1	\$70.50				-
38	Radiator air guide CM	1	\$46.72				
39	Radiator lower air guide	1	\$102.63				7
40	Radiator upper air guide	1	\$ 77.22				1
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58		0					
_	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

<u>Labour</u>

Vehicle No.		SLM3239Z	Case Owner	:	Andrew	
Make & Model	:	M/BENZ E 200	Year of Manufacture	3	2012	

S/No	Labour Description	Esimated Price	Adjusted Price
1	Labor to panel beat, repair and to replace front damaged parts	\$ 1,000.00	6001
	and affected areas		
2	To check lighting and wiring	\$ 50.00	201
3	To putty and spray paint front bumper, bonnet, LH front fender,	\$ 1,000.00	8001
	RH front fender and affected areas		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any $additional\ damages\ observed\ during\ the\ course\ of\ repair\ will\ be\ quote\ accordingly\ as\ a\ supplementary.$